cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 18272 Main St		eet: MCLAUGHLIN_DR	Cross Street: MONROE_RD					Location:	NE	
ADA ID: F4D65577C965 Ramp T		ype: PerpDiag Init		al Pass/Fail: Fail Overall Compliance: No			o Severity Score:	26.25		
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
	C AUCHUN DR	Possible Solutions:	Co	Compliance Description Data Compliance Description						
		Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Surveyor Notes: N/A			Ramp Length (in)	52.0	No	Ramp Slope (%)	13.5	
			Ye		Ramp Width (in)	48.0		Ramp XSlope (%)	2.9	
ativ .			N//	4	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
			N//	A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
			N//	A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
			N//	A	Landing Length (in)		N/A	DWS Provided?	N/A	
			N//	A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
			N//	A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
			N//	A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
	A CONTRACTOR OF THE OWNER OWNER OF THE OWNER OWNE		N//	A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
the second s			N//	A	Shared Landing?	N/A				
		PROW/ADA:	N//	A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
	EAL	R304.2.2, R304.5.3	N//	4	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
			N//	A	Painted X Walk1?	No	N/A	Painted X Walk2?	No	
	Siller Forthe March				X Walk 1 Direction	To W		X Walk 2 Direction	To S	
			N//	A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	MONROE RD	-			X Walk 1 Slope (%)	2.7		X Walk 2 Slope (%)	0.9	
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	1.2		X Walk 2 X Slope (%)	1.4	
Street 2 Name	MCLAUGHLIN DR		N//	A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	StopSign				Road Slope (%)	0.5	N/A	Clear Space?	N/A	
					Road X Slope (%)	2.2	N/A	Clear Space to XWalk (in)	N/A	
			N/2	A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost: \$ 320	00.00		Obstruction Type			Storm Grate/Utility Type		
					••	N/A			N/A	
							Yes	Surface Condition? (G/P)	Good	

