

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 8141 Main St	8141 Main Street: CROSSRIDGE_RD			RUNNING_DEER_RD	Location:	N/A		
								8.75
· · · ·							0.75	
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance						
Tresserves an guardian (at	Possible Solutions:	Compliance Description D			Data	Data Compliance Description		Data
	Remove & Replace Entire Ramp		N/A	Ramp Length (in)	104.5	Yes	Ramp Slope (%)	6.4
the second of the second of	×		No	Ramp Width (in)	47.0	Yes	Ramp XSlope (%)	1.3
A CARLES AND A CARLES	5		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
en e			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	-		N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
the second secon	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	-		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
			N/A	Shared Landing?	N/A			
	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	Not Found, R304.5.1		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
				X Walk 1 Direction	To W		X Walk 2 Direction	N/A
	2		N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name RUNNING DEER RD				X Walk 1 Slope (%)	6.4		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2 None				X Walk 1 X Slope (%)	1.3		X Walk 2 X Slope (%)	N/A
Street 2 Name N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1 N/A				Road Slope (%)	1.3	N/A	Clear Space?	N/A
				Road X Slope (%)	6.4	N/A	Clear Space to XWalk (in)	N/A
			N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Total Cost: \$	850.00		Obstruction Type			Storm Grate/Utility Type	
					N/A			N/A

**Yes** Surface Condition? (G/P)

Good

