


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: N/A	Main Street: CROSS POINT CIR	Cross Street: NORTHEAST PWY	Location: SE
ADA ID: F54117468F99	Ramp Type: PerpDiag	Initial Pass/Fail: Fail	Overall Compliance: No
		Severity Score: 50	

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance			
	Possible Solutions:		Compliance	Description	Data	
	Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.		N/A	Ramp Length (in)	62.0	No
			Yes	Ramp Width (in)	48.0	No
			N/A	Flare Type LT	N/A	N/A
			N/A	Flare Slope LT (%)	N/A	N/A
			N/A	Flare Traversable LT?	No	N/A
			N/A	Landing Length (in)	N/A	N/A
			N/A	Landing Width (in)	N/A	N/A
			N/A	Landing Slope (%)	N/A	N/A
			N/A	Landing X Slope (%)	N/A	N/A
			N/A	Landing Curb? (Y/N)	N/A	N/A
			N/A	Shared Landing?	N/A	
			N/A	Gutter Ponding?	N/A	N/A
			N/A	Gutter Lip Ht (in)	N/A	N/A
			N/A	Painted X Walk1?	No	N/A
				X Walk 1 Direction	To N	To W
			N/A	X Walk 1 Width (in)	N/A	N/A
				X Walk 1 Slope (%)	1.2	
				X Walk 1 X Slope (%)	8.1	
			N/A	Ramp inside XWalk1?	N/A	N/A
<p>Surveyor Notes:</p> <p>N/A</p>				Road Slope (%)	7.5	N/A
				Road X Slope (%)	2.5	N/A
<p>PROW/ADA:</p> <p>Not Found, R304.2.2, R304.5.3</p>			N/A	Any Obstructions?	N/A	N/A
				Obstruction Type		
Total Cost: \$ 3200.00					N/A	N/A
					Yes	Surface Condition? (G/P) Good

