

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 9451 Main Street: BREWTON_DR				<u> </u>						
Intersection ID: 9451	Main Sti	Cross Street: EUREKA_ST				Location:	SE			
ADA ID: F59E1DD25865	Ramp Type: Perp			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	50	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
1 The second sec	AL SA	Possible Solutions:		Compliance Description Data			Compliance Description		Data	
	A M	Remove & Replace Entire Ramp		N/A	Ramp Length (in)	64.0	No	Ramp Slope (%)	18.9	
Parts 1		-		Yes	Ramp Width (in)	96.0	No	Ramp XSlope (%)	15.7	
The second second	No. 1			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
D C N LONG				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
Elizaber		2		N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
TOLOW	the start is	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
<u>.</u>	100	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
	NYAMA L			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
	S. W. Ca			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
a state of the second	AL A			N/A	Shared Landing?	N/A				
5 11	with a l	PROW/ADA:		N/A	Gutter Ponding?	Yes	N/A	Gutter Slope (%)	N/A	
	-Berger	R304.2.2, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
		·····,····		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
	N K COM				X Walk 1 Direction	To N		X Walk 2 Direction	N/A	
	ha the			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	EUREKA ST				X Walk 1 Slope (%)	0.6		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	0.8		X Walk 2 X Slope (%)	N/A	
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A	
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type		
						N/A			N/A	

s Surface Condition? (G/P)

Good

