


# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

Intersection ID: 24025	Main Street: SOUTH_LAKES_DR	Cross Street: SOUTH_RIDGE_DR	Location: N
ADA ID: F5A5866865A2	Ramp Type: Perp	Initial Pass/Fail: Fail	Overall Compliance: No
Severity Score: 13.75			
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance	

	Possible Solutions:						
	Remove & Replace Entire Ramp.						
	Surveyor Notes:						
	N/A						
	PROW/ADA:						
	Not Found, R304.2.2, R304.5.3						
				Compliance	Description	Data	Compliance
				Description			Description
				Data			Data
				N/A	Ramp Length (in)	68.0	No
				Yes	Ramp Width (in)	48.0	No
				N/A	Flare Type LT	N/A	N/A
				N/A	Flare Slope LT (%)	N/A	N/A
				N/A	Flare Traversable LT?	N/A	N/A
				N/A	Landing Length (in)	N/A	N/A
				N/A	Landing Width (in)	N/A	N/A
				N/A	Landing Slope (%)	N/A	N/A
				N/A	Landing X Slope (%)	N/A	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A
				N/A	Shared Landing?	N/A	N/A
				N/A	Gutter Ponding?	N/A	N/A
				N/A	Gutter Lip Ht (in)	N/A	N/A
				N/A	Painted X Walk1?	No	N/A
					X Walk 1 Direction	To S	
				N/A	X Walk 1 Width (in)	N/A	N/A
					X Walk 1 Slope (%)	4.9	
					X Walk 1 X Slope (%)	1.4	
				N/A	Ramp inside XWalk1?	N/A	N/A
					Road Slope (%)	N/A	N/A
					Road X Slope (%)	N/A	N/A
				N/A	Any Obstructions?	N/A	N/A
					Obstruction Type		
						N/A	N/A
						Yes	Surface Condition? (G/P)
							Good

