

Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 43535	Main Street: AMBROSIA_ST	Cross Street: PLANTERS_WATCH_DR	Location: W
ADA ID: F5A5D035BD78	Ramp Type: PerpDiag	Initial Pass/Fail: Fail	Overall Compliance: No
		Severity Score: 35	

Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance			
 Street 1 Name AMBROSIA ST Stop Condition-Street 2 StopSign Street 2 Name PLANTERS WATCH DR Stop Condition-Street 1 None	Possible Solutions:	Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.			
	Surveyor Notes:	N/A			
	PROW/ADA:	R304.5.1, R304.2.2, R304.5.3			
			Compliance	Description	Data
			No	Ramp Length (in)	47.5
			No	Ramp Width (in)	38.0
			N/A	Flare Type LT	N/A
			N/A	Flare Slope LT (%)	N/A
			N/A	Flare Traversable LT?	N/A
			N/A	Landing Length (in)	N/A
			N/A	Landing Width (in)	N/A
			N/A	Landing Slope (%)	N/A
			N/A	Landing X Slope (%)	N/A
			N/A	Landing Curb? (Y/N)	N/A
			N/A	Shared Landing?	N/A
			N/A	Gutter Ponding?	N/A
			N/A	Gutter Lip Ht (in)	N/A
			No	Painted X Walk1?	No
			To SE	X Walk 1 Direction	To NE
			N/A	X Walk 1 Width (in)	N/A
			2.0	X Walk 1 Slope (%)	1.2
			4.1	X Walk 1 X Slope (%)	3.7
			N/A	Ramp inside XWalk1?	N/A
			3.5	Road Slope (%)	N/A
			1.9	Road X Slope (%)	N/A
			N/A	Any Obstructions?	N/A
			N/A	Obstruction Type	N/A
			N/A		N/A
			Yes	Surface Condition? (G/P)	Good
Total Cost:		\$ 3200.00			

