## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



		•	-	-					
Intersection ID: 27896	Main Str	Main Street: PARADISE_RIDGE_RD			RUSSIAN_RIVER_PL	Location:	NW		
ADA ID: F5C5F748E13B	Ramp Ty	Ramp Type: PerpDiag			ail: Fail Overall C	o Severity Score:	30		
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description			Data Compliance Description		
		Remove & Replace Curb Ramp	Vith	N/A	Ramp Length (in)	48.0	No	Ramp Slope (%)	9.4
		Two New Directional Ramps or		No	Ramp Width (in)	35.0	Yes	Ramp XSlope (%)	0.5
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
		1		N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
The second second		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
NORE RIDE	alle of			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
FAIring				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A			
PROW/ADA: Not Found, R304.5.1, R304.2.2				N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
					X Walk 1 Direction	To S		X Walk 2 Direction	To E
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	PARADISE RIDGE RD	-			X Walk 1 Slope (%)	1.4		X Walk 2 Slope (%)	4.5
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	2.7		X Walk 2 X Slope (%)	2.3
Street 2 Name	RUSSIAN RIVER PL			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	StopSign				Road Slope (%)	2.1	N/A	Clear Space?	N/A
	ctopolyn				Road X Slope (%)	4.3	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	4.0 N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 3	200.00		Obstruction Type			Storm Grate/Utility Type	
		······ ••••				N/A			N/A
						10/4			

Yes Surface Condition? (G/P)

Good

