## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 16707	Main Stree	Main Street: BEVERLY_DR				HAMPTON_AV		Location:	NW	
ADA ID: F5F13033681B	Ramp Typ	Ramp Type: Combination2Diag			Initial Pass/Fail: Fail Overall Complian				o Severity Score:	0
Codes/I	Mitigation Info/P	ossible Solution				Field Measure	ments/C	ompo	nent Compliance	
		Possible Solutions:			Compliance Description		Data Compliance Description		liance Description	Data
	a de to	Remove & Replace Cu			N/A	Ramp Length LT (in)	N/A	N/A	Ramp Length RT (in)	32.0
	V-AL	Two New Directional Ramps or Equivalent.			N/A	Ramp Width LT (in)	N/A	Yes	Ramp Width RT (in)	53.0
				N/A	Ramp Slope LT (%)	N/A	Yes	Ramp Slope RT (%)	7.0	
		Surveyor Notes:			N/A	Ramp XSlope LT (%)	N/A	No	Ramp XSlope RT (%)	4.0
					N/A	Ramp Length (in)	32.0	Yes	Ramp Slope (%)	6.3
	BET L'AN				No	Ramp Width (in)	42.5	No	Ramp XSlope (%)	2.1
	ç			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
		N/A			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
TRIVER	and all the state			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
EIAVIAN 12 6	5. Mill Think				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
5	The second				N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	The second se	PROW/ADA:			N/A	Landing Slope (%)		N/A	DWS Length (in)	N/A
	THE BI	Not Found, R304.5.1, R304.5.3		3	N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				5	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
					N/A	Shared Landing?	N/A			
	12 100 16	N TA			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
Street 1 Name	None				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
Stop Condition-Street 1	BEVERLY DR				N/A	Painted X Walk1?	No		Painted X Walk2?	No
Street 2 Name	StopSign					X Walk 1 Direction	To S		X Walk 2 Direction	To E
Stop Condition-Street 2	HAMPTON AV					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
						X Walk 1 Slope (%)	1.2		X Walk 2 Slope (%)	7.0
						X Walk 1 X Slope (%)	2.1		X Walk 2 X Slope (%)	1.9
	-	Total Cost:	\$	3200.00	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
			Ŧ		••••	Road Slope (%)	4.6		Clear Space?	N/A
						Road X Slope (%)	2.5	N/A	Clear Space to XWalk (in)	N/A
				. *				N/A	Any Obstruction?	N/A
				1. 1. 1. 1. 1.		A A A A A A A A A A A A A A A A A A A			Obstruction Type	
						Hold Same				N/A
	and the second second		-			-		N/A	Storm Grate/Utility Hazard?	N/A

N/A Storm Grate/Utility Hazard? N/A Storm Grate/Utility Type N/A Yes Surface Condition? (G/P) Good Curb Slope (%) 6.0





