

## **Access Compliance Report** Public Rights-of-Way (Curb Ramps)



Intersection ID: 10025398	25398 Main Street: E_ARROWOOD_RD			Cross Street: N/A					NE
ADA ID: F637F3FB4F73	FB4F73 Ramp Type: Perp			Initial Pass/Fail: Fail Overall Compliance: No					37.5
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance						
		Possible Solutions:					liance Description	Data	
A A A A A A A A A A A A A A A A A A A		Remove & Replace Entire Ramp	. N/.	A	Ramp Length (in)	52.0	No	Ramp Slope (%)	11.3
	100		Ye	s	Ramp Width (in)	96.0	No	Ramp XSlope (%)	10.1
			N/2	Α	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	the Jacobson of a		N/.	A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	C. C. C. P. C. S.		N/.	A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
Martine R La Contra			N/.	A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
THE REAL PROPERTY OF		Surveyor Notes:	N/	A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
ter		N/A	N/	A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
E ARROWO			N/	A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	The second		N/	Α	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
the second second second	the state of the s		N/	Α	Shared Landing?	N/A			
6 6 6 6	A CONTRACTOR AND	PROW/ADA:	N/	Α	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
to man and the second		R304.2.2, R304.5.3	N/2	Α	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
The Party of the	BU DE DUTINGS		N/	Α	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
	C. Sandistilla				X Walk 1 Direction	To S		X Walk 2 Direction	N/A
	Tente El Cale Cale		N/	Α	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	E ARROWOOD RD				X Walk 1 Slope (%)	7.3		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	8.0		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A		N/	Α	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
			N/.	Α	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 1	850.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A
							Yes	Surface Condition? (G/P)	Good





