


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 19337	Main Street: PARK_RD	Cross Street: N/A	Location: NE
ADA ID: F692E1C56B1F	Ramp Type: PerpDiag	Initial Pass/Fail: Fail	Overall Compliance: No
			Severity Score: 21.25

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance		
	Possible Solutions:		Compliance	Description	Data
	Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.		N/A	Ramp Length (in)	47.0
			No	Ramp Width (in)	43.0
			N/A	Flare Type LT	N/A
			N/A	Flare Slope LT (%)	N/A
			N/A	Flare Traversable LT?	N/A
			N/A	Landing Length (in)	N/A
			N/A	Landing Width (in)	N/A
			N/A	Landing Slope (%)	N/A
			N/A	Landing X Slope (%)	N/A
<p>Surveyor Notes:</p> <p>N/A</p> <p>PROW/ADA:</p> <p>R304.5.1, R304.5.3</p>			N/A	Flare Type RT	N/A
			N/A	Flare Slope RT (%)	N/A
			N/A	Flare Traversable RT?	N/A
			N/A	DWS Provided?	N/A
			N/A	DWS Contrast?	N/A
			N/A	DWS Length (in)	N/A
			N/A	DWS Full Width?	N/A
			N/A	DWS Offset (in)	N/A
			N/A	Shared Landing?	N/A
			N/A	Gutter Ponding?	N/A
<p>Total Cost:</p> <p>\$ 3200.00</p>			N/A	Gutter Lip Ht (in)	N/A
			N/A	Painted X Walk1?	Yes
				X Walk 1 Direction	To W
			N/A	X Walk 1 Width (in)	86.0
				X Walk 1 Slope (%)	0.1
				X Walk 1 X Slope (%)	0.6
			N/A	Ramp inside XWalk1?	Yes
				Road Slope (%)	3.2
				Road X Slope (%)	1.6
			N/A	Any Obstructions?	N/A
				Obstruction Type	
			N/A	Ramp inside XWalk2?	Yes
				Clear Space?	N/A
				Clear Space to XWalk (in)	N/A
			N/A	Storm Grate/Utility Hazard?	N/A
				Storm Grate/Utility Type	
			N/A	Surface Condition? (G/P)	N/A
			Yes		Good

