

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 2838 Main Street: FOGGY_MEADOW_RD Cross Street: LONG_FOREST_DR Location: ADA ID: F6A6D1D5400C Ramp Type: Perp Initial Pass/Fail: Fail Overall Compliance: No Severity Score	SW
ADA ID: F6A6D1D5400C Ramp Type: Perp Initial Pass/Fail: Fail Overall Compliance: No Severity Score	4.95
	1.25
Codes/Mitigation Info/Possible Solution Field Measurements/Component Compliance	
Compliance Description Data Compliance Description	Data
Remove & Replace Entire Ramp. N/A Ramp Length (in) 50.0 Yes Ramp Slope (%)	7.3
Yes Ramp Width (in) 48.0 No Ramp XSlope (%)	4.4
N/A Flare Type LT N/A N/A Flare Type RT	N/A
N/A Flare Slope LT (%) N/A Flare Slope RT (%)	N/A
N/A Flare Traversable LT? N/A N/A Flare Traversable RT?	N/A
ROCOV_MEND N/A Landing Length (in) N/A N/A DWS Provided? Surveyor Notes: N/A Landing Width (in) N/A N/A DWS Contrast?	N/A
Surveyor Notes: N/A Landing Width (in) N/A N/A DWS Contrast?	N/A
المعادمة م	N/A
N/A Landing X Slope (%) N/A DWS Full Width?	N/A
	N/A
N/A Shared Landing? N/A	
N/A Landing Curb? (Y/N) N/A N/A DWS Offset (in) N/A Shared Landing? N/A N/A Gutter Slope (%) N/A Gutter Lip Ht (in) N/A Gutter X Slope (%) N/A Painted X Walk1? No N/A	N/A
R304.5.3 N/A Gutter Lip Ht (in) N/A N/A Gutter X Slope (%)	N/A
N/A Painted X Walk1? No N/A Painted X Walk2?	N/A
X Walk 1 Direction To E X Walk 2 Direction	N/A
N/A X Walk 1 Width (in) N/A N/A X Walk 2 Width (in)	N/A
Street 1 Name LONG FOREST DR X Walk 1 Slope (%) 1.5 X Walk 2 Slope (%)	N/A
Stop Condition-Street 2StopSignX Walk 1 X Slope (%)5.6X Walk 2 X Slope (%)	N/A
Street 2 Name N/A N/A Ramp inside XWalk1? N/A Ramp inside XWalk2?	N/A
Stop Condition-Street 1 N/A N/A Clear Space?	N/A
Road X Slope (%) N/A N/A Clear Space to XWalk (in)	N/A
N/A Any Obstructions? N/A N/A Storm Grate/Utility Hazard?	N/A
Total Cost: \$ 1850.00 Obstruction Type Storm Grate/Utility Type	
N/A	N/A

Yes Surface Condition? (G/P)

Good

