


Access Compliance Report

Public Rights-of-Way (Curb Ramps)

| | | | |
|---|--------------------------------|---|------------------------|
| Intersection ID: 51509 | Main Street: EASTFIELD_PARK_DR | Cross Street: NETHERTON_LN | Location: S |
| ADA ID: F6C1C7282E29 | Ramp Type: Perp | Initial Pass/Fail: Pass | Overall Compliance: No |
| Severity Score: 5 | | | |
| Codes/Mitigation Info/Possible Solution | | Field Measurements/Component Compliance | |



Possible Solutions:

**Remove & Replace Entire Ramp.
Remove & Replace Gutter.**

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R305.2, R304.5.4

Total Cost: \$ 2600.00

| Compliance | Description | Data | Compliance | Description | Data |
|------------|-----------------------|--------|------------|-----------------------------|------|
| N/A | Ramp Length (in) | 71.0 | Yes | Ramp Slope (%) | 6.2 |
| Yes | Ramp Width (in) | 48.0 | Yes | Ramp XSlope (%) | 0.6 |
| N/A | Flare Type LT | Sloped | N/A | Flare Type RT | N/A |
| N/A | Flare Slope LT (%) | 2.4 | Yes | Flare Slope RT (%) | 3.3 |
| N/A | Flare Traversable LT? | No | N/A | Flare Traversable RT? | Yes |
| Yes | Landing Length (in) | 59.5 | Yes | DWS Provided? | Yes |
| Yes | Landing Width (in) | 87.0 | Yes | DWS Contrast? | Yes |
| Yes | Landing Slope (%) | 1.8 | Yes | DWS Length (in) | 24.0 |
| Yes | Landing X Slope (%) | 1.9 | Yes | DWS Full Width? | Yes |
| N/A | Landing Curb? (Y/N) | No | No | DWS Offset (in) | 4.0 |
| N/A | Shared Landing? | No | | | |
| Yes | Gutter Ponding? | No | No | Gutter Slope (%) | 5.2 |
| Yes | Gutter Lip Ht (in) | 0.0 | Yes | Gutter X Slope (%) | 1.1 |
| N/A | Painted X Walk1? | No | N/A | Painted X Walk2? | N/A |
| | X Walk 1 Direction | To NE | | X Walk 2 Direction | N/A |
| N/A | X Walk 1 Width (in) | N/A | N/A | X Walk 2 Width (in) | N/A |
| | X Walk 1 Slope (%) | 2.6 | | X Walk 2 Slope (%) | N/A |
| | X Walk 1 X Slope (%) | 1.2 | | X Walk 2 X Slope (%) | N/A |
| N/A | Ramp inside XWalk1? | N/A | N/A | Ramp inside XWalk2? | N/A |
| | Road Slope (%) | N/A | N/A | Clear Space? | Yes |
| | Road X Slope (%) | N/A | N/A | Clear Space to XWalk (in) | N/A |
| Yes | Any Obstructions? | No | Yes | Storm Grate/Utility Hazard? | No |
| | Obstruction Type | | | Storm Grate/Utility Type | |
| | | N/A | | | N/A |
| | | | Yes | Surface Condition? (G/P) | Good |

Street 1 Name EASTFIELD PARK DR
Stop Condition-Street 2 None
Street 2 Name N/A
Stop Condition-Street 1 N/A

