cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 28276 Main Street: LONG_COVE_DR			Cross	Cross Street: TOM_SHORT_RD				Location:	NW
ADA ID: F6CF581311D	ID: F6CF581311D1 Ramp Type: PerpDiag		Initial F	Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	33.75
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description			Data Compliance Description		
	The	Remove & Replace Curb Ramp W Two New Directional Ramps or Equivalent.	Nith	N/A	Ramp Length (in)	50.0	No	Ramp Slope (%)	13.7
				No	Ramp Width (in)	43.0	Yes	Ramp XSlope (%)	1.8
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
2 Delaya	100 - 100 -			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	THE PROPERTY			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	NG_GOVE_DR	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
E E		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
		1/2		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
PROW/ADA: Not Found, R304.5.1, R304.2.2				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A			
				N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
					X Walk 1 Direction	To W		X Walk 2 Direction	To S
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	TOM SHORT RD			10/4	X Walk 1 Slope (%)	2.1		X Walk 2 Slope (%)	1.4
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	2.1		X Walk 2 X Slope (%)	1.4
Street 2 Name	LONG COVE DR			N/A	Ramp inside XWalk1?	2.3 N/A	N/A	Ramp inside XWalk2?	N/A
				N/A		1.5	N/A		N/A N/A
Stop Condition-Street 1	StopSign				Road Slope (%)			Clear Space?	
				N1/A	Road X Slope (%)	0.4	N/A	Clear Space to XWalk (in)	N/A
		T-1-1-0		N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 3	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

STOP



Yes

Surface Condition? (G/P)

Good