## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: N/A	Main Street: DELUCA_DR				Cross Street: HAMEL_ST			Location: NW		
ADA ID: F6D8ED83BF61	Ramp Type: Combination2Diag			Initial	Initial Pass/Fail: Fail Overall Complian			nce: No Severity Score: (		0
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
		Possible Solutions:			Comp	liance Description	nce Description Data		Compliance Description	
	5 23 3 5	Remove & Replace C	urb Ramı	o With	N/A	Ramp Length LT (in)	29.5	N/A	Ramp Length RT (in)	22.0
		Two New Directional			No	Ramp Width LT (in)	47.5	No	Ramp Width RT (in)	47.0
		Equivalent.			Yes	Ramp Slope LT (%)	7.2	Yes	Ramp Slope RT (%)	3.2
					No	Ramp XSlope LT (%)	2.5	Yes	Ramp XSlope RT (%)	0.7
A CEALLE					N/A	Ramp Length (in)	47.0	Yes	Ramp Slope (%)	3.0
					No	Ramp Width (in)	47.0	No	Ramp XSlope (%)	3.3
RUTEL ST G		Surveyor Notes:			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
		N/A			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
					N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
					N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
					N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		PROW/ADA:			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
		Not Found, R304.5.1, R304.5.1, R304.5.3		1.	N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				- ,	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
					N/A	Shared Landing?	N/A			
					N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
Street 1 Name	StopSign				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
Stop Condition-Street 1	DELUCA DR				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
Street 2 Name	None					X Walk 1 Direction	To S		X Walk 2 Direction	To E
Stop Condition-Street 2	HAMEL ST					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
						X Walk 1 Slope (%)	4.3		X Walk 2 Slope (%)	1.6
						X Walk 1 X Slope (%)	0.2		X Walk 2 X Slope (%)	5.1
		Total Cost:	\$	3200.00	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
						Road Slope (%)	3.4		Clear Space?	N/A
						Road X Slope (%)	5.3	N/A	Clear Space to XWalk (in)	N/A
			12		1			N/A	Any Obstruction?	N/A
									Obstruction Type	
				1	5	A REAL PROPERTY AND IN THE REAL PROPERTY AND INTERPORT AND				N/A
				1) and				N/A	Storm Grate/Utility Hazard?	N/A
			1		Alt March 19				Storm Grate/Utility Type	17/7

Storm Grate/Utility Type
N/A
Yes Surface Condition? (G/P) Good
Curb Slope (%) 13.5





