

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

6.0

0.1

N/A

Good

Intersection ID: 5672 Main Street: SUNSET\_RD Cross Street: BEATTIES\_FORD\_RD Location: NW

ADA ID: F75A842A5B8F Ramp Type: Perp Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 8.75

Compliance Description

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Landing Length (in)

Landing Width (in)

Landing Slope (%)

Landing X Slope (%)

Landing Curb? (Y/N)

Shared Landing?

**Gutter Ponding?** 

Gutter Lip Ht (in)

Painted X Walk1?

X Walk 1 Direction

X Walk 1 Width (in)

X Walk 1 Slope (%)

X Walk 1 X Slope (%)

Ramp inside XWalk1?

Road Slope (%)

Road X Slope (%)

Any Obstructions?

**Obstruction Type** 

Flare Traversable LT?

Flare Type LT

N/A

No

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance

Yes

Yes

N/A

Yes

Compliance Description

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

**DWS Provided?** 

**DWS Contrast?** 

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

X Walk 2 Slope (%)

X Walk 2 X Slope (%)

Ramp inside XWalk2?

Clear Space to XWalk (in)

Storm Grate/Utility Type

Surface Condition? (G/P)

Storm Grate/Utility Hazard?

Clear Space?

Flare Traversable RT?

Data

59.0

42.5

N/A

Yes

To SE

98.0

1.0

1.0

Yes

N/A

N/A

N/A

N/A



Street 1 Name
SUNSET RD
Stop Condition-Street 2
Signal
Street 2 Name
N/A
Stop Condition-Street 1
N/A

OSSIBIC COIDLION
Possible Solutions:
Remove & Replace Entire Ramp.
O
Surveyor Notes:
N/A
PROW/ADA:
Not Found, R304.5.1

N/A
N/A
PROW/ADA:
Not Found, R304.5.1

N/A
N/A
N/A

N/A

N/A

N/A

Total Cost:
\$ 1850.00



