

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



		-							
Intersection ID: 18484	Main Str	eet: FOXCROFT_WOODS_LN	l Cro	Cross Street: SHARON_RD				Location:	NW
ADA ID: F7664A18764F	Ramp Type: Directional1			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	12.5
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	E E E E E E E E E E E E E E E E E E E	Possible Solutions:		Compliance Description Date			a Compliance Description		Data
1		Remove & Replace Entire R	lamp.	N/A	Ramp Length (in)	52.0	N/A	Grade Break?	N/A
			•	Yes	Ramp Width (in)	54.0	N/A	Grade Break Slope (%)	0.0
rajast - to the				Yes	Ramp Slope (%)	0.3	N/A	Grade Break XSlope (%)	0.0
				No	Ramp XSlope (%)	6.2			
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
a the second second				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0
		Surveyor Notes:		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
A BARRADA		N/A		N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A
TEN RD				N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A
MOODHLAN				N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A
		PROW/ADA:		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A
		R304.5.3		N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A
And the state of the				N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A
A CONTRACTOR OF THE OWNER OWNER OF THE OWNER OWN				N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	No		Road Slope (%)	3.2
Street 1 Name	WOODHAVEN RD				X Walk 1 Direction	To S		Road X Slope (%)	2.9
Stop Condition-Street 1	StopSign				X Walk 1 Width (in)	N/A		Clear Space?	N/A
Street 2 Name	N/A				X Walk 1 Slope (%)	3.2	N/A	Clear Space to XWalk (in)	N/A
Stop Condition-Street 2	N/A				X Walk 1 X Slope (%)	2.9	N/A	Storm Grate/Utility Hazard?	N/A
				N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type	
				N/A	Any Obstructions?	N/A			N/A
		Total Cost: \$	1600.0	)	Obstruction Type		Yes	Surface Condition? (G/P)	Good
						N/A	N/A	Curb Slope (%)	4.9

