


Access Compliance Report

Public Rights-of-Way (Curb Ramps)

Intersection ID: 24700	Main Street: HARLEQUIN_DR	Cross Street: WHISTLING_DUCK_CT	Location: SE
ADA ID: F78BDA23B497	Ramp Type: Directional1	Initial Pass/Fail: Fail	Overall Compliance: No
			Severity Score: 21.25

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance							
	Possible Solutions:		Compliance			Description			Data	
	Remove & Replace Entire Ramp.		N/A	Ramp Length (in)	53.0	N/A	Grade Break?	N/A		
			No	Ramp Width (in)	44.0	N/A	Grade Break Slope (%)	0.0		
			Yes	Ramp Slope (%)	3.3	N/A	Grade Break XSlope (%)	0.0		
			No	Ramp XSlope (%)	6.7					
			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A		
			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0		
			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A		
			N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A		
			N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A		
Surveyor Notes:		N/A			N/A			Landing Slope (%)	0.0	N/A
PROW/ADA:		R304.5.1, R304.5.3			N/A			Landing X Slope (%)	0.0	N/A
					N/A			Landing Curb? (Y/N)	N/A	N/A
					N/A			Shared Landing?	N/A	N/A
					N/A			Gutter Ponding?	0.0	N/A
					N/A			Gutter Lip Ht (in)	0.0	N/A
					N/A			Painted X Walk1?	No	N/A
					To SW			Road Slope (%)	2.2	N/A
					N/A			Road X Slope (%)	0.5	N/A
					N/A			Clear Space?	N/A	N/A
					N/A			Clear Space to XWalk (in)	N/A	N/A
					N/A			Storm Grate/Utility Hazard?	N/A	N/A
					N/A			Storm Grate/Utility Type		N/A
					N/A					N/A
					Yes			Surface Condition? (G/P)	Good	
					N/A			Curb Slope (%)	8.1	

