

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 28397 Main Street: COMMONS\_CROSSING\_DR Cross Street: WADE\_ARDREY\_RD Location: NW

ADA ID: F81EBD28E473 Ramp Type: Perp Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 21.25

## Codes/Mitigation Info/Possible Solution



Street 1 Name
WADE ARDREY RD
Stop Condition-Street 2
None
Street 2 Name
N/A
Stop Condition-Street 1
N/A

Possible Solutions:	2
Remove & Replace Entire Ramp.	ı
	ı
	ı
	ı
	ı
	ı
Surveyor Notes:	ı
N/A	I
	ı
	I
	I
PROW/ADA:	I
Not Found, R304.5.1, R304.2.2	ı
	I
	I



Total Cost:



1850.00

Field Measurements/Component Compliance							
Compliance Description		Data	Comp	liance Description	Data		
N/A	Ramp Length (in)	93.0	No	Ramp Slope (%)	8.7		
No	Ramp Width (in)	40.0	Yes	Ramp XSlope (%)	1.9		
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A		
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A		
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A		
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A		
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A		
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A		
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A		
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A		
N/A	Shared Landing?	N/A					
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A		
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A		
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A		
	X Walk 1 Direction	To S		X Walk 2 Direction	N/A		
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A		
	X Walk 1 Slope (%)	4.6		X Walk 2 Slope (%)	N/A		
	X Walk 1 X Slope (%)	1.9		X Walk 2 X Slope (%)	N/A		
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A		
	Road Slope (%)	N/A	N/A	Clear Space?	N/A		
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A		
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A		
	Obstruction Type			Storm Grate/Utility Type			
		N/A			N/A		
			Yes	Surface Condition? (G/P)	Good		