

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

43.0

60.5

5.1

0.9

3.0

2.6

N/A

Good 11.2

Intersection ID: 4752 Main Street: EVANSHIRE_DR Cross Street: TRINITY_RD Location: W

ADA ID: F875E53B2A61 Ramp Type: Combination1 Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 18.75

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name
StopSign
Stop Condition-Street 1
Street 2 Name
N/A
Stop Condition-Street 2
N/A

Possible Solutions:

Remove & Replace Entire Ramp.


Surveyor Notes:

RP & LT RP < 5%

PROW/ADA:

Not Found, R304.5.1, R304.5.3

Total Cost: \$



N/A

N/A

N/A

N/A

N/A

N/A

N/A

Yes

Ramp inside XWalk2?

Clear Space to XWalk (in)

Storm Grate/Utility Hazard?

Storm Grate/Utility Type

Surface Condition? (G/P)

Clear Space?

Any Obstruction?

Obstruction Type

Curb Slope (%)







N/A

Ramp inside XWalk1?

Road Slope (%)

1800.00