

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 11112Main Street:WILKINSON_BVCross Street:LITTLE_ROCK_RDLocation:NEADA ID: F88163AAC9A3Ramp Type:PerpInitial Pass/Fail:FailOverall Compliance:NoSeverity Score:10

Codes/Mitigation Info/Possible Solution



Street 1 Name	LITTLE ROCK RD
Stop Condition-Street 2	StopSign
Street 2 Name	N/A
Stop Condition-Street 1	N/A

i ossible odlation	
Possible Solutions:	<u>c</u>
Remove & Replace Entire Ramp.	
·	N
	N
	N
	N
	N
Surveyor Notes:	N
N/A	N
	N
	N
	N
PROW/ADA:	N
Not Found, R304.5.1, R304.5.3	N
	N
	N

Total Cost:	\$ 1850.0	

Field Measurements/Component Compliance							
Comp	liance Description	Data	Comp	oliance Description	Data		
N/A	Ramp Length (in)	44.5	Yes	Ramp Slope (%)	5.0		
No	Ramp Width (in)	47.5	No	Ramp XSlope (%)	2.8		
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A		
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A		
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A		
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A		
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A		
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A		
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A		
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A		
N/A	Shared Landing?	N/A					
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A		
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A		
N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A		
	X Walk 1 Direction	To W		X Walk 2 Direction	N/A		
N/A	X Walk 1 Width (in)	112.0	N/A	X Walk 2 Width (in)	N/A		
	X Walk 1 Slope (%)	0.7		X Walk 2 Slope (%)	N/A		
	X Walk 1 X Slope (%)	3.2		X Walk 2 X Slope (%)	N/A		
N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A		
	Road Slope (%)	N/A	N/A	Clear Space?	N/A		
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A		
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A		
	Obstruction Type			Storm Grate/Utility Type			
		N/A			N/A		
			Yes	Surface Condition? (G/P)	Good		
1	1 1						





