

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 44165	Main Street: COCHRANE_DR			Cross Street: FOUNTAINGRASS_LN				Location:	NW
ADA ID: F8BF181D04D9	Ramp Type: PerpDiag			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	47.5
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:						liance Description	Data
		Remove & Replace Curb Ram	With	N/A	Ramp Length (in)	82.0	Yes	Ramp Slope (%)	5.7
		Two New Directional Ramps of		No	Ramp Width (in)	23.0	No	Ramp XSlope (%)	6.1
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
		-		N/A	Flare Slope LT (%)		N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A		Flare Traversable RT?	N/A
		-		N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
Photo		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
OPTICA				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
Good	the sease of the			N/A	Landing Curb? (Y/N)	N/A		DWS Offset (in)	N/A
and the second				N/A	Shared Landing?	N/A			
	IC GREAM	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
- 20		Not Found, R304.5.1, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
		Not i ound, 1004.5.1, 1004.5.5		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
TAK OV - TALAN				X Walk 1 Direction	To S		X Walk 2 Direction	To E	
	四日 白之州、东			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	COCHRANE DR	-			X Walk 1 Slope (%)	0.1		X Walk 2 Slope (%)	3.3
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	4.7		X Walk 2 X Slope (%)	1.7
Street 2 Name	FOUNTAINGRASS LN			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	StopSign				Road Slope (%)	4.0	N/A	Clear Space?	N/A
					Road X Slope (%)	1.6	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A		Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
		·			51	N/A			N/A
						•			

Yes Surface Condition? (G/P)

Good



