

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 3577	77 Main Street: CROFTON_SPRINGS_DR			Cross Street: LAUREL_CREST_CT			Location:	NW	
ADA ID: F8D2518CFB0A	CFB0A Ramp Type: Directional1		Initial Pass/Fail: Fail Overall Complian			nce: No	Severity Score:	10	
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance						
	/	Possible Solutions:	Co	Compliance Description			Data Compliance Description		
	8	Remove & Replace Entire Ramp	N/4	Ramp Lengt	th (in) 48.0	N/A	Grade Break?	N/A	
			No	Ramp Width	n (in) 41.0	N/A	Grade Break Slope (%)	0.0	
	<u>g</u>		Yes	Ramp Slope	e (%) 5.2	N/A	Grade Break XSlope (%)	0.0	
	<u>S</u> I		No	Ramp XSlop	be (%) 4.3				
			N/#	Flare Type L	T N/A	N/A	Flare Type RT	N/A	
			N/#	Flare Slope	LT (%) N/A	N/A	Flare Slope RT (%)	0.0	
	? /	Surveyor Notes:	N/#	Flare Traver	sable LT? N/A	N/A	Flare Traversable RT?	N/A	
LAUREL GREAT		N/A	N/A	Landing Len	gth (in) 0.0	N/A	DWS Provided?	N/A	
To_Testson_GT	/		N/A	Landing Wid	Ith (in) 0.0	N/A	DWS Contrast?	N/A	
<u>ل</u>			N/#	Landing Slop	pe (%) 0.0	N/A	DWS Length (in)	N/A	
			N/#	Landing X S	lope (%) 0.0	N/A	DWS Full Width?	N/A	
l l j		PROW/ADA:	N/#	Landing Cur	b? (Y/N) N/A	N/A	DWS Offset LT (in)	N/A	
		R304.5.1, R304.5.3	N/A	Shared Land	ding? N/A	N/A	DWS Offset RT (in)	N/A	
			N/#	Gutter Pond	ling? 0.0	N/A	Gutter Slope (%)	N/A	
			N/A	Gutter Lip H	t (in) 0.0	N/A	Gutter X Slope (%)	N/A	
			N/#	Painted X W	/alk1? No		Road Slope (%)	4.1	
Street 1 Name	LAUREL CREST CT			X Walk 1 Dir	rection To S		Road X Slope (%)	2.8	
Stop Condition-Street 1	StopSign			X Walk 1 Wi	dth (in) N/A		Clear Space?	N/A	
Street 2 Name	N/A			X Walk 1 Slo	ope (%) 4.1	N/A	Clear Space to XWalk (in)	N/A	
Stop Condition-Street 2	N/A			X Walk 1 X S	Slope (%) 2.8	N/A	Storm Grate/Utility Hazard?	N/A	
			N/#	Ramp inside	XWalk1? N/A		Storm Grate/Utility Type		
			N/#	Any Obstruc	tions? N/A			N/A	
		Total Cost: \$ 1	600.00	Obstruction	Туре	Yes	Surface Condition? (G/P)	Good	
					N/A	N/A	Curb Slope (%)	12.6	

