## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: N/A Main Street: PINEVILLE-MATTHEWS_RD 0					oss Street: N/A				SW
ADA ID: F90FD799752B Ramp Type: PerpDiag				itial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	13.75
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	A STATE AND A STATE	Possible Solutions:		Compliance Description Data Complian			liance Description	Data	
and the second second	THE RD	Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.	/ith	N/A	Ramp Length (in)	45.0	No	Ramp Slope (%)	9.8
				Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	2.3
A CAR THE				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
A REAL PROPERTY OF				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	MANUELLE			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
THENLILE				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
Filmer	5	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	the second second	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
and the	and I have been all	4		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
A A				N/A	Shared Landing?	N/A			
and the second	Di la	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
E Sal ach	2007	R304.2.2, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
acons	······		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No	
and the second sec					X Walk 1 Direction	To E		X Walk 2 Direction	To N
19.00 30 000	Property Property in			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	ENTRANCE	-			X Walk 1 Slope (%)	0.5		X Walk 2 Slope (%)	6.0
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	1.2		X Walk 2 X Slope (%)	1.5
Street 2 Name	PINEVILLE-MATTHEWS RD			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	None				Road Slope (%)	1.6	N/A	Clear Space?	N/A
					Road X Slope (%)	4.7	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 32	200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A		5 51	N/A
4						-	I		<b>.</b> .

Yes Surface Condition? (G/P)

Good





