

# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

|                                         |                              |                                         |                        |
|-----------------------------------------|------------------------------|-----------------------------------------|------------------------|
| Intersection ID: 10020275               | Main Street: AYRSLEY_TOWN_BV | Cross Street: N/A                       | Location: NW           |
| ADA ID: F95941651FEB                    | Ramp Type: BlendTrans2       | Initial Pass/Fail: Pass                 | Overall Compliance: No |
| Severity Score: 0                       |                              |                                         |                        |
| Codes/Mitigation Info/Possible Solution |                              | Field Measurements/Component Compliance |                        |



Possible Solutions:

**Remove & Replace Detectable Warning System. Remove & Replace Gutter.**

Surveyor Notes:

**N/A**

PROW/ADA:

**R305.2, R304.5.3**

Total Cost: \$ 1550.00

| Compliance | Description           | Data                  | Compliance | Description                 | Data                  |
|------------|-----------------------|-----------------------|------------|-----------------------------|-----------------------|
| N/A        | Ramp Length (in)      | 201.0                 | Yes        | BlendTrans Slope (%)        | 1.7                   |
| Yes        | Ramp Width (in)       | 120.0                 | Yes        | BlendTrans XSlope (%)       | 1.4                   |
| Yes        | Flare Type            | LCurbed_NoWalkSurface | Yes        | Flare Type                  | RCurbed_NoWalkSurface |
| N/A        | Flare Slope LT (%)    | N/A                   | N/A        | Flare Slope RT (%)          | N/A                   |
| N/A        | Flare Traversable LT? | No                    | N/A        | Flare Traversable RT?       | No                    |
| N/A        | Landing Length (in)   | N/A                   | Yes        | DWS Provided?               | Yes                   |
| N/A        | Landing Width (in)    | N/A                   | Yes        | DWS Contrast?               | Yes                   |
| N/A        | Landing Slope (%)     | N/A                   | Yes        | DWS Length (in)             | 24.0                  |
| N/A        | Landing X Slope (%)   | N/A                   | Yes        | DWS Full Width?             | Yes                   |
| N/A        | Landing Curb? (Y/N)   | No                    | No         | DWS Offset (in)             | 2.5                   |
| N/A        | Shared Landing?       | No                    |            |                             |                       |
| Yes        | Gutter Ponding?       | No                    | Yes        | Gutter Slope (%)            | 1.5                   |
| Yes        | Gutter Lip Ht (in)    | 0.0                   | No         | Gutter X Slope (%)          | 3.9                   |
| N/A        | Painted X Walk1?      | No                    | N/A        | Painted X Walk2?            | N/A                   |
|            | X Walk 1 Direction    | To SW                 |            | X Walk 2 Direction          | N/A                   |
|            | X Walk 1 Width (in)   | N/A                   |            | X Walk 2 Width (in)         | N/A                   |
|            | X Walk 1 Slope (%)    | 1.9                   |            | X Walk 2 Slope (%)          | N/A                   |
|            | X Walk 1 X Slope (%)  | 2.5                   |            | X Walk 2 X Slope (%)        | N/A                   |
| N/A        | Ramp inside XWalk1?   | N/A                   | N/A        | Ramp inside XWalk2?         | N/A                   |
|            | Road Slope (%)        | 2.5                   |            | Clear Space?                | Yes                   |
|            | Road X Slope (%)      | 1.9                   | N/A        | Clear Space to XWalk (in)   | N/A                   |
| Yes        | Any Obstructions?     | No                    | Yes        | Storm Grate/Utility Hazard? | No                    |
|            | Obstruction Type      |                       |            | Storm Grate/Utility Type    |                       |
|            |                       |                       | N/A        |                             | N/A                   |
|            |                       |                       | Yes        | Surface Condition? (G/P)    | Good                  |
|            |                       |                       | Yes        | Curb Slope (%)              | 0.3                   |

Street 1 Name AYRSLEY TOWN BV

Stop Condition-Street 1 None

Street 2 Name N/A

Stop Condition-Street 2 N/A

