## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 24557	: 24557 Main Street: PARK_CROSSING_DR		Cross	Street:	WARWICK_CR	Location:	SW		
ADA ID: F9DE0E6A78E6	ADA ID: F9DE0E6A78E6 Ramp Type: PerpDiag			nitial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	25
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description		Data Compliance Description		Data	
10 million and		Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.	Vith	N/A	Ramp Length (in)	33.0	No	Ramp Slope (%)	9.4
A State of the second sec				Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	5.3
A A A A A A A A A A A A A A A A A A A				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
A MA COMPANY AND A MARKED				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
PARK GROS	SIMO			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	Le la	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
La Carte Carta Car		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
the second se				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
53				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
			N/A	Shared Landing?	N/A				
	A Had -	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	A CARE DO	R304.2.2, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
					X Walk 1 Direction	To E		X Walk 2 Direction	To N
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	WARWICK CREST LN	-			X Walk 1 Slope (%)	5.1		X Walk 2 Slope (%)	2.2
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	1.4		X Walk 2 X Slope (%)	5.3
Street 2 Name	PARK CROSSING DR			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	None				Road Slope (%)	6.3	N/A	Clear Space?	N/A
					Road X Slope (%)	6.0	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 3	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P) Good

