

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 50476 Main Street: BOW RD **Cross Street: KINGS RIDGE DR** Location: **ADA ID: F9EE0BB58311** Ramp Type: PerpDiag Initial Pass/Fail: Fail **Overall Compliance: No** Severity Score: 21.25

Codes/Mitigation Info/Possible Solution

BOW RD

KINGS RIDGE DR

None

None

Field Measurements/Component Compliance



Street 1 Name Stop Condition-Street 2 Street 2 Name Stop Condition-Street 1 Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.5.1, R304.5.3

Comp	liance Description	Data	Comp	liance	Description	Data
N/A	Ramp Length (in)	58.5	Yes	Ramp	Slope (%)	7.9
No	Ramp Width (in)	44.5	No	Ramp	XSlope (%)	5.5
N/A	Flare Type LT	N/A	N/A	Flare	Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A
N/A	Landing Length (in)	N/A	N/A	DWS	Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS	Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS	Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A
N/A	Shared Landing?	N/A				
N/A	Gutter Ponding?	N/A	N/A	Gutte	Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutte	X Slope (%)	N/A
N/A	Painted X Walk1?	No	N/A	Painte	ed X Walk2?	No
	X Walk 1 Direction	To SW		X Wal	k 2 Direction	To SE
N/A	X Walk 1 Width (in)	N/A	N/A	X Wal	k 2 Width (in)	N/A
	X Walk 1 Slope (%)	2.4		X Wal	k 2 Slope (%)	9.5
	X Walk 1 X Slope (%)	7.1		X Wal	k 2 X Slope (%)	0.5
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp	inside XWalk2?	N/A
	Road Slope (%)	4.9	N/A	Clear	Space?	N/A
	Road X Slope (%)	2.6	N/A	Clear	Space to XWalk (in)	N/A
N/A	Any Obstructions?	N/A	N/A	Storm	Grate/Utility Hazard?	N/A
	Obstruction Type		l	Storm	Grate/Utility Type	
		N/A				N/A

Yes

Surface Condition? (G/P)

Good





Total Cost:



3200.00