## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

Surface Condition? (G/P)

Good

Intersection ID: 10035790 Main Street: REMOUNT_RD					Cross Street: N/A				Location:	N	
Intersection ID: 10035790											
ADA ID: F9FA94CF64BC Ramp Type: Perp			Initial F	Initial Pass/Fail: Fail Overall Compliance: No				Severity Score:	13.75		
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance						
2 1 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	W JACK	Possible Solutions:		Compliance Description D			Data	ta Compliance Description Data			
No. A AND		Remove & Replace En	tire Ramp		N/A	Ramp Length (in)	121.0	No	Ramp Slope (%)	8.8	
			•		Yes	Ramp Width (in)	141.0	No	Ramp XSlope (%)	2.7	
					N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
A Contraction					N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
and the second second	14. 9				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
	1 30				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
and the second second	1 1/2	Surveyor Notes:			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
A A C	The	N/A			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
A CONTRACTOR	A. P.				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
6 6 C					N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
0	A A A				N/A	Shared Landing?	N/A				
	0 " 1	PROW/ADA:			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
	A CONTRACT	Not Found, R304.2.2, F	R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
	1 the man				N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A	
	1.0					X Walk 1 Direction	To SW		X Walk 2 Direction	N/A	
2 1 . M 1 B PC					N/A	X Walk 1 Width (in)	136.0	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	REMOUNT RD					X Walk 1 Slope (%)	0.3		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 2	None					X Walk 1 X Slope (%)	0.2		X Walk 2 X Slope (%)	N/A	
Street 2 Name	N/A				N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	N/A					Road Slope (%)	N/A	N/A	Clear Space?	N/A	
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
					N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost:	\$	1850.00		Obstruction Type			Storm Grate/Utility Type		
							N/A			N/A	

