


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: N/A		Main Street: CITY_PARK_DR		Cross Street: ARBOR_LOOP_DR		Location:		W	
ADA ID: F9FB7C5180AF		Ramp Type: Directional1		Initial Pass/Fail: Fail		Overall Compliance: No		Severity Score: 1.25	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
<div></div> <div>Possible Solutions:</div> <div>Remove & Replace Entire Ramp.</div> <div>Surveyor Notes:</div> <div>N/A</div> <div>PROW/ADA:</div> <div>R304.5.3</div> <div>Street 1 Name</div> <div>NATIONAL AV</div> <div>Stop Condition-Street 1</div> <div>StopSign</div> <div>Street 2 Name</div> <div>N/A</div> <div>Stop Condition-Street 2</div> <div>N/A</div> <div>Total Cost:</div> <div>\$</div> <div>1600.00</div>				Compliance	Description	Data	Compliance	Description	Data
				N/A	Ramp Length (in)	98.0	N/A	Grade Break?	N/A
				Yes	Ramp Width (in)	72.0	N/A	Grade Break Slope (%)	0.0
				Yes	Ramp Slope (%)	3.0	N/A	Grade Break XSlope (%)	0.0
				No	Ramp XSlope (%)	3.7			
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A
				N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A
				N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A
				N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A
				N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A
				N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	Yes		Road Slope (%)	3.8
					X Walk 1 Direction	To N		Road X Slope (%)	2.2
					X Walk 1 Width (in)	96.0		Clear Space?	N/A
					X Walk 1 Slope (%)	3.8	N/A	Clear Space to XWalk (in)	N/A
					X Walk 1 X Slope (%)	2.2	N/A	Storm Grate/Utility Hazard?	N/A
				N/A	Ramp inside XWalk1?	Yes		Storm Grate/Utility Type	
				N/A	Any Obstructions?	N/A			N/A
					Obstruction Type		Yes	Surface Condition? (G/P)	Good
							N/A	Curb Slope (%)	4.4

Street 1 Name	NATIONAL AV
Stop Condition-Street 1	StopSign
Street 2 Name	N/A
Stop Condition-Street 2	N/A

