## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 12427	Main Street: W_STONEWALL_ST				S_MINT_ST		Location:	W	
ADA ID: FA590D057BC5	Ramp Ty	Ramp Type: BlendTrans1			ail: Pass Overall	ce: N	e: No Severity Score:		
Cod	es/Mitigation Info/	Possible Solution			Field Measure	ements/C	ompo	nent Compliance	
		Possible Solutions:		Compliance Description		Data	Data Compliance Description		Data
		Remove & Replace Landing.		N/A	Ramp Length (in)	60.0	Yes	BlendTrans Slope (%)	1.8
		Restripe Crosswalk(s) To Provid	de	Yes	Ramp Width (in)	258.0	Yes	BlendTrans XSlope (%)	1.8
	<u>ь</u>	Clear space. Relocate Obstructi	on.	N/A	Flare Type LT	Sloped	N/A	Flare Type RT	Sloped
				N/A	Flare Slope LT (%)	6.3	N/A	Flare Slope RT (%)	5.0
				N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	No
	A Am			Yes	Landing Length (in)	60.0	Yes	DWS Provided?	Yes
		Surveyor Notes:		Yes	Landing Width (in)	60.0	Yes	DWS Contrast?	Yes
		N/A		No	Landing Slope (%)	2.4	Yes	DWS Length (in)	24.0
				No	Landing X Slope (%)	2.7	Yes	DWS Full Width?	Yes
In the second second	R			N/A	Landing Curb? (Y/N)	No	Yes	DWS Offset (in)	2.0
The second second	No.			N/A	Shared Landing?	No			
1 A 1 A 1 A 1 A 1 A 1 A 1 A 1 A 1 A 1 A		PROW/ADA:		Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	0.5
La carrier a la la	de la	R304.2.2-Perp, R304.3.2-Para,		Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	0.9
and the second	· > 100	R304.5.3, Not Found, R207.1,		N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	Yes
and with the state of the state		R302.3, R402.2			X Walk 1 Direction	To SE		X Walk 2 Direction	To NE
The state I B					X Walk 1 Width (in)	116.0		X Walk 2 Width (in)	111.0
Street 1 Name	S MINT ST				X Walk 1 Slope (%)	2.2		X Walk 2 Slope (%)	1.7
Stop Condition-Street 1	Signal				X Walk 1 X Slope (%)	1.1		X Walk 2 X Slope (%)	0.5
Street 2 Name	W STONEWALL ST			Yes	Ramp inside XWalk1?	Yes	No	Ramp inside XWalk2?	No
Stop Condition-Street 2	Signal				Road Slope (%)	0.7		Clear Space?	Yes
					Road X Slope (%)	1.8	No	Clear Space to XWalk (in)	28.0
				No	Any Obstructions?	Yes	Yes	Storm Grate/Utility Hazard?	No
		Total Cost: \$ 2	2000.00		Obstruction Type			Storm Grate/Utility Type	
					OTHER: FOOTBALL STADIL	JM POLES			N/A
							Yes	Surface Condition? (G/P)	Good
							Yes	Curb Slope (%)	3.7



