

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 22376 Main Street: CREEK VALLEY DR **Cross Street: SARDIS RD** Location:

ADA ID: FAECE986E7BB Ramp Type: PerpDiag Initial Pass/Fail: Fail **Overall Compliance: No** Severity Score: 33.75

Codes/Mitigation Info/Possible Solution



Street 1 Name Stop Condition-Street 2 Street 2 Name Stop Condition-Street 1

SARDIS RD None **CREEK VALLEY DR** StopSign

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Surveyor Notes:

PROW/ADA:

N/A

R304.5.1, R304.5.3

| / | | |
|---|--|--|



Total Cost:



3200.00

| Field Measurements/Component Compliance | | | | | | | | |
|-----------------------------------------|-----------------------|-------|------|-----------------------------|-------|--|--|--|
| Comp | liance Description | Data | Comp | liance Description | Data | | | |
| N/A | Ramp Length (in) | 59.0 | Yes | Ramp Slope (%) | 6.9 | | | |
| No | Ramp Width (in) | 47.0 | No | Ramp XSlope (%) | 8.0 | | | |
| N/A | Flare Type LT | N/A | N/A | Flare Type RT | N/A | | | |
| N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | N/A | | | |
| N/A | Flare Traversable LT? | N/A | N/A | Flare Traversable RT? | N/A | | | |
| N/A | Landing Length (in) | N/A | N/A | DWS Provided? | N/A | | | |
| N/A | Landing Width (in) | N/A | N/A | DWS Contrast? | N/A | | | |
| N/A | Landing Slope (%) | N/A | N/A | DWS Length (in) | N/A | | | |
| N/A | Landing X Slope (%) | N/A | N/A | DWS Full Width? | N/A | | | |
| N/A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset (in) | N/A | | | |
| N/A | Shared Landing? | N/A | | | | | | |
| N/A | Gutter Ponding? | N/A | N/A | Gutter Slope (%) | N/A | | | |
| N/A | Gutter Lip Ht (in) | N/A | N/A | Gutter X Slope (%) | N/A | | | |
| N/A | Painted X Walk1? | No | N/A | Painted X Walk2? | No | | | |
| | X Walk 1 Direction | To SW | | X Walk 2 Direction | To SE | | | |
| N/A | X Walk 1 Width (in) | N/A | N/A | X Walk 2 Width (in) | N/A | | | |
| | X Walk 1 Slope (%) | 5.8 | | X Walk 2 Slope (%) | 4.5 | | | |
| | X Walk 1 X Slope (%) | 1.5 | | X Walk 2 X Slope (%) | 8.4 | | | |
| N/A | Ramp inside XWalk1? | N/A | N/A | Ramp inside XWalk2? | N/A | | | |
| | Road Slope (%) | 8.9 | N/A | Clear Space? | N/A | | | |
| | Road X Slope (%) | 4.5 | N/A | Clear Space to XWalk (in) | N/A | | | |
| N/A | Any Obstructions? | N/A | N/A | Storm Grate/Utility Hazard? | N/A | | | |
| | Obstruction Type | | | Storm Grate/Utility Type | | | | |
| | | N/A | | | N/A | | | |
| | | | Yes | Surface Condition? (G/P) | Good | | | |