

# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

|   |                                |   |                        |
|---|--------------------------------|---|------------------------|
| Intersection ID: 45882                  | Main Street: HOMESTEAD_GLEN_BV | Cross Street: VALLEYDALE_RD             | Location: E            |
| ADA ID: FB339D1571BC                    | Ramp Type: Combination1        | Initial Pass/Fail: Fail                 | Overall Compliance: No |
| Codes/Mitigation Info/Possible Solution |                                | Field Measurements/Component Compliance |                        |



Possible Solutions:

**Remove & Replace Entire Ramp.**

Surveyor Notes:

**RP < 5%**

PROW/ADA:

**Not Found, R304.3.2**

|                         |               |
|-------------------------|---------------|
| Street 1 Name           | None          |
| Stop Condition-Street 1 | VALLEYDALE RD |
| Street 2 Name           | N/A           |
| Stop Condition-Street 2 | N/A           |

Total Cost: \$ 1800.00

| Compliance | Description           | Data  | Compliance | Description                 | Data |
|------------|-----------------------|-------|------------|-----------------------------|------|
| N/A        | Ramp Length LT (in)   | 52.0  | N/A        | Ramp Length RT (in)         | 46.0 |
| Yes        | Ramp Width LT (in)    | 60.0  | Yes        | Ramp Width RT (in)          | 60.0 |
| Yes        | Ramp Slope LT (%)     | 5.5   | No         | Ramp Slope RT (%)           | 11.9 |
| Yes        | Ramp XSlope LT (%)    | 0.7   | Yes        | Ramp XSlope RT (%)          | 0.2  |
| N/A        | Ramp Length (in)      | 46.5  | Yes        | Ramp Slope (%)              | 2.9  |
| Yes        | Ramp Width (in)       | 49.0  | Yes        | Ramp XSlope (%)             | 2.8  |
| N/A        | Flare Type LT         | N/A   | N/A        | Flare Type RT               | N/A  |
| N/A        | Flare Slope LT (%)    | N/A   | N/A        | Flare Slope RT (%)          | N/A  |
| N/A        | Flare Traversable LT? | N/A   | N/A        | Flare Traversable RT?       | N/A  |
| N/A        | Landing Length (in)   | N/A   | N/A        | DWS Provided?               | N/A  |
| N/A        | Landing Width (in)    | N/A   | N/A        | DWS Contrast?               | N/A  |
| N/A        | Landing Slope (%)     | N/A   | N/A        | DWS Length (in)             | N/A  |
| N/A        | Landing X Slope (%)   | N/A   | N/A        | DWS Full Width?             | N/A  |
| N/A        | Landing Curb? (Y/N)   | N/A   | N/A        | DWS Offset (in)             | N/A  |
| N/A        | Shared Landing?       | N/A   |            |                             |      |
| N/A        | Gutter Ponding?       | N/A   | N/A        | Gutter Slope (%)            | N/A  |
| N/A        | Gutter Lip Ht (in)    | N/A   | N/A        | Gutter X Slope (%)          | N/A  |
| N/A        | Painted X Walk1?      | No    | N/A        | Painted X Walk2?            | N/A  |
|            | X Walk 1 Direction    | To SW |            | X Walk 2 Direction          | N/A  |
|            | X Walk 1 Width (in)   | N/A   |            | X Walk 2 Width (in)         | N/A  |
|            | X Walk 1 Slope (%)    | 1.1   |            | X Walk 2 Slope (%)          | N/A  |
|            | X Walk 1 X Slope (%)  | 3.0   |            | X Walk 2 X Slope (%)        | N/A  |
| N/A        | Ramp inside XWalk1?   | N/A   | N/A        | Ramp inside XWalk2?         | N/A  |
|            | Road Slope (%)        | N/A   |            | Clear Space?                | N/A  |
|            | Road X Slope (%)      | N/A   | N/A        | Clear Space to XWalk (in)   | N/A  |
|            |                       |       | N/A        | Any Obstruction?            | N/A  |
|            |                       |       |            | Obstruction Type            | N/A  |
|            |                       |       | N/A        | Storm Grate/Utility Hazard? | N/A  |
|            |                       |       |            | Storm Grate/Utility Type    | N/A  |
|            |                       |       | Yes        | Surface Condition? (G/P)    | Good |
|            |                       |       |            | Curb Slope (%)              | 18.1 |

