

Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

| | | | |
|------------------------|-------------------------|------------------------------|------------------------|
| Intersection ID: 50608 | Main Street: DENBUR_DR | Cross Street: DOWNY_BIRCH_RD | Location: NW |
| ADA ID: FB6844329054 | Ramp Type: Combination2 | Initial Pass/Fail: Fail | Overall Compliance: No |
| | | | Severity Score: 13.75 |

| Codes/Mitigation Info/Possible Solution | | | Field Measurements/Component Compliance | | | |
|---------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------|--|-----------------------------------------|-----------------------------|-------------|--------------------|
|  | Possible Solutions: | | Compliance | Description | Data | Compliance |
| | Remove & Replace Entire Ramp. | | Description | | | Description |
| | | | Data | | | Data |
| | | | N/A | Ramp Length LT (in) | 44.5 | N/A |
| | | | N/A | Ramp Width LT (in) | 58.0 | Yes |
| | | | N/A | Ramp Slope LT (%) | 1.7 | No |
| | | | N/A | Ramp XSlope LT (%) | 1.1 | No |
| | | | N/A | Ramp Length (in) | 48.0 | Yes |
| | | | Yes | Ramp Width (in) | 48.0 | No |
| | | | N/A | Ramp XSlope (%) | | 2.2 |
| <p>Surveyor Notes:</p> <p>LT RP < 5%</p> <p>PROW/ADA:</p> <p>Not Found, R304.5.3, R304.3.2</p> | | | N/A | Flare Type LT | N/A | N/A |
| | | | N/A | Flare Slope LT (%) | N/A | N/A |
| | | | N/A | Flare Traversable LT? | N/A | N/A |
| | | | N/A | Flare Traversable RT? | N/A | N/A |
| | | | N/A | Landing Length (in) | N/A | N/A |
| | | | N/A | Landing Width (in) | N/A | N/A |
| | | | N/A | Landing Slope (%) | N/A | N/A |
| | | | N/A | Landing X Slope (%) | N/A | N/A |
| | | | N/A | Landing Curb? (Y/N) | N/A | N/A |
| | | | N/A | DWS Provided? | N/A | N/A |
| <p>Total Cost:</p> <p>\$ 1600.00</p> | | | N/A | DWS Contrast? | N/A | N/A |
| | | | N/A | DWS Length (in) | N/A | N/A |
| | | | N/A | DWS Full Width? | N/A | N/A |
| | | | N/A | DWS Offset (in) | N/A | N/A |
| | | | N/A | Shared Landing? | N/A | N/A |
| | | | N/A | Gutter Ponding? | N/A | N/A |
| | | | N/A | Gutter Slope (%) | N/A | N/A |
| | | | N/A | Gutter Lip Ht (in) | N/A | N/A |
| | | | N/A | Gutter X Slope (%) | N/A | N/A |
| | | | N/A | Painted X Walk1? | No | N/A |
| <p>Street 1 Name</p> <p>Stop Condition-Street 1</p> <p>Street 2 Name</p> <p>Stop Condition-Street 2</p> | | | N/A | Painted X Walk2? | N/A | N/A |
| | | | N/A | X Walk 1 Direction | To SE | N/A |
| | | | N/A | X Walk 2 Direction | | N/A |
| | | | N/A | X Walk 1 Width (in) | N/A | N/A |
| | | | N/A | X Walk 2 Width (in) | | N/A |
| | | | N/A | X Walk 1 Slope (%) | 3.4 | N/A |
| | | | N/A | X Walk 2 Slope (%) | | N/A |
| | | | N/A | X Walk 1 X Slope (%) | 1.1 | N/A |
| | | | N/A | X Walk 2 X Slope (%) | | N/A |
| | | | N/A | Ramp inside XWalk1? | N/A | N/A |
| <p>Street 1 Name</p> <p>Stop Sign</p> <p>Downy Birch Rd</p> <p>Street 2 Name</p> <p>N/A</p> <p>Stop Condition-Street 2</p> <p>N/A</p> | | | N/A | Ramp inside XWalk2? | N/A | N/A |
| | | | N/A | Road Slope (%) | N/A | N/A |
| | | | N/A | Clear Space? | N/A | N/A |
| | | | N/A | Clear Space to XWalk (in) | N/A | N/A |
| | | | N/A | Any Obstruction? | N/A | N/A |
| | | | N/A | Obstruction Type | | N/A |
| | | | N/A | Storm Grate/Utility Hazard? | N/A | N/A |
| | | | N/A | Storm Grate/Utility Type | | N/A |
| | | | N/A | Surface Condition? (G/P) | Yes | Good |
| | | | N/A | Curb Slope (%) | | 10.7 |

