

Access Compliance Report Public Rights-of-Way (Curb Ramps)



										I
Intersection ID: 28714	tersection ID: 28714 Main Street: EAGLE_CREEK_DR			Cross	Cross Street: KEITHWOOD_PL				Location:	W
ADA ID: FBC95A36AC1C	ID: FBC95A36AC1C Ramp Type: Directional1			Initial	Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	22.5
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
		Possible Solutions:			Comp	liance Description	Data	Comp	liance Description	Data
		Remove & Replace Ent	ire Ram	D .	N/A	Ramp Length (in)	33.0	N/A	Grade Break?	N/A
		•		•	No	Ramp Width (in)	47.0	N/A	Grade Break Slope (%)	0.0
					No	Ramp Slope (%)	8.6	N/A	Grade Break XSlope (%)	0.0
					No	Ramp XSlope (%)	3.0			
A A A A A A A A A A A A A A A A A A A					N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
L'OIIII					N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0
ALE COLORING COLORING		Surveyor Notes:			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
L		N/A			N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A
					N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A
K 1					N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A
8					N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A
		PROW/ADA:			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A
		R304.5.1, R304.2.2, R3	04.5.3		N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A
		,,			N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A
					N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A
					N/A	Painted X Walk1?	No		Road Slope (%)	1.1
Street 1 Name	KEITHWOOD PL					X Walk 1 Direction	To SE		Road X Slope (%)	1.7
Stop Condition-Street 1	StopSign					X Walk 1 Width (in)	N/A		Clear Space?	N/A
Street 2 Name	N/A					X Walk 1 Slope (%)	1.1	N/A	Clear Space to XWalk (in)	N/A
Stop Condition-Street 2	N/A					X Walk 1 X Slope (%)	1.7	N/A	Storm Grate/Utility Hazard?	N/A
					N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type	
					N/A	Any Obstructions?	N/A			N/A
		Total Cost:	\$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good
							N/A	N/A	Curb Slope (%)	N/A

