

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 29164 Main Street: GARRISON_RD Cross Street: PURPLE_BLOOM_LN Location: S

ADA ID: FBD9B32C7359 Ramp Type: PerpDiag Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 33.75

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 2
Street 2 Name
Stop Condition-Street 1

PURPLE BLOOM LN None GARRISON RD StopSign Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.5.1, R304.5.3

Total Cost: \$ 3200.00

Field Measurements/Component Compliance							
	Comp	liance Description	Data	Comp	liance D	escription	Data
	N/A	Ramp Length (in)	49.5	Yes	Ramp SI	lope (%)	6.9
	No	Ramp Width (in)	40.0	No	Ramp X	Slope (%)	15.9
	N/A	Flare Type LT	N/A	N/A	Flare Ty	pe RT	N/A
	N/A	Flare Slope LT (%)	N/A	N/A	Flare Slo	ope RT (%)	N/A
	N/A	Flare Traversable LT?	N/A	N/A	Flare Tra	aversable RT?	N/A
	N/A	Landing Length (in)	N/A	N/A	DWS Pr	ovided?	N/A
	N/A	Landing Width (in)	N/A	N/A	DWS Co	ontrast?	N/A
	N/A	Landing Slope (%)	N/A	N/A	DWS Le	ngth (in)	N/A
	N/A	Landing X Slope (%)	N/A	N/A	DWS Fu	II Width?	N/A
	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Of	fset (in)	N/A
	N/A	Shared Landing?	N/A				
	N/A	Gutter Ponding?	N/A	N/A	Gutter S	lope (%)	N/A
	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X	Slope (%)	N/A
	N/A	Painted X Walk1?	No	N/A	Painted	X Walk2?	No
		X Walk 1 Direction	To NE		X Walk 2	2 Direction	To NW
	N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2	2 Width (in)	N/A
		X Walk 1 Slope (%)	3.4		X Walk 2	2 Slope (%)	5.2
		X Walk 1 X Slope (%)	10.9		X Walk 2	2 X Slope (%)	10.4
	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp in	side XWalk2?	N/A
		Road Slope (%)	12.9	N/A	Clear Sp	pace?	N/A
		Road X Slope (%)	2.3	N/A	Clear Sp	pace to XWalk (in)	N/A
	N/A	Any Obstructions?	N/A	N/A	Storm G	rate/Utility Hazard?	N/A
		Obstruction Type			Storm G	rate/Utility Type	
			N/A				N/A
				Yes	Surface	Condition? (G/P)	Good





