cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 23321	Main Street: BALLENTYNE_CT		Cross Street: GLENEAGLES_RD			Location:	SW
ADA ID: FBE2E49ACE58	Ramp Type: PerpDiag		nitial Pass/Fail: Fail Overall Compliance:			o Severity Score:	25
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance				
	Possible Solutions:	Con	Compliance Description Da		a Compliance Description		Data
	Remove & Replace Curb Ramp V	Vith N/A	Ramp Length (in)	42.0	No	Ramp Slope (%)	13.4
	Two New Directional Ramps or	Yes	Ramp Width (in)	48.0	Yes	Ramp XSlope (%)	1.6
	Equivalent.	N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
GRI SEUDAEIXELID		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
		N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	Surveyor Notes:	N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	N/A	N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	A CARL	N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
TO MY COM	the second se	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	Mar 1	N/A	Shared Landing?	N/A			
	PROW/ADA:	N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
a contraction of the	Not Found, R304.2.2	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	B	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
	W. Con		X Walk 1 Direction	To E		X Walk 2 Direction	To N
		N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name BALLEN	TYNE CT		X Walk 1 Slope (%)	4.9		X Walk 2 Slope (%)	6.9
Stop Condition-Street 2	StopSign		X Walk 1 X Slope (%)	5.9		X Walk 2 X Slope (%)	3.7
Street 2 Name GLENEAG	GLES RD	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	None		Road Slope (%)	7.7	N/A	Clear Space?	N/A
			Road X Slope (%)	9.1	N/A	Clear Space to XWalk (in)	N/A
		N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Total Cost: \$ 3	200.00	Obstruction Type			Storm Grate/Utility Type	
				N/A			N/A

Yes Surface Condition? (G/P)

Good

