


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 45157	Main Street: ROBIN_TERRY_CT	Cross Street: MACVEAN_LN	Location: SW
ADA ID: FC0AFD651791	Ramp Type: PerpDiag	Initial Pass/Fail: Fail	Overall Compliance: No
Severity Score: 10			
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance	

	Possible Solutions:		Compliance		Description		Data	Compliance		Description		Data
	Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.		N/A	Ramp Length (in)	48.0	Yes	Ramp Slope (%)	6.2				
			No	Ramp Width (in)	36.0	No	Ramp XSlope (%)	2.6				
			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A				
			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A				
			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A				
			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A				
			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A				
			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A				
			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A				
Surveyor Notes:		N/A	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A				
		N/A	Shared Landing?	N/A								
		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A					
		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A					
		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No					
			X Walk 1 Direction	To E		X Walk 2 Direction	To N					
		N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A					
			X Walk 1 Slope (%)	1.9		X Walk 2 Slope (%)	5.2					
			X Walk 1 X Slope (%)	4.8		X Walk 2 X Slope (%)	1.4					
		N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A					
			Road Slope (%)	1.8	N/A	Clear Space?	N/A					
			Road X Slope (%)	6.0	N/A	Clear Space to XWalk (in)	N/A					
		N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A					
			Obstruction Type			Storm Grate/Utility Type						
					N/A		N/A					
					Yes	Surface Condition? (G/P)	Good					
							</					

