

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10032672 Main Street: N_KINGS_DR Cross Street: N/A Location: Severity Score: 13.75 Ramp Type: Directional1 **Overall Compliance: No ADA ID: FC106AE843C6** Initial Pass/Fail: Fail

Codes/Mitigation Info/Possible Solution



Street 1 Name	ENTRANCE
Stop Condition-Street 1	StopSign
Street 2 Name	N/A
Stop Condition-Street 2	N/A

Possible Solutions: Remove & Replace Entire Ramp. Surveyor Notes: N/A PROW/ADA: R304.2.2, R304.5.3

Total Cost:	\$ 1600.00	

Field Measurements/Component Compliance						
Compl	iance Description	Data	Comp	liance Description	Data	
N/A	Ramp Length (in)	52.0	N/A	Grade Break?	N/A	
Yes	Ramp Width (in)	68.0	N/A	Grade Break Slope (%)	0.0	
No	Ramp Slope (%)	11.5	N/A	Grade Break XSlope (%)	0.0	
No	Ramp XSlope (%)	3.9				
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0	
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A	
N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A	
N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A	
N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A	
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A	
N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A	
N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A	
N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A	
N/A	Painted X Walk1?	No		Road Slope (%)	2.5	
	X Walk 1 Direction	To SW		Road X Slope (%)	2.1	
	X Walk 1 Width (in)	N/A		Clear Space?	N/A	
	X Walk 1 Slope (%)	2.5	N/A	Clear Space to XWalk (in)	N/A	
	X Walk 1 X Slope (%)	2.1	N/A	Storm Grate/Utility Hazard?	N/A	
N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type		
N/A	Any Obstructions?	N/A			N/A	
	Obstruction Type		Yes	Surface Condition? (G/P)	Good	
		N/A	N/A	Curb Slope (%)	11.3	





