

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 12013 Main Street: FREEDOM\_DR Cross Street: W\_MOREHEAD\_ST Location: SW

ADA ID: FC5C3DC837F7 Ramp Type: Perp Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 8.75

Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance

Yes

Surface Condition? (G/P)

Good



A CONTRACTOR OF THE PARTY OF TH	A COMPANY OF THE PARTY.
Street 1 Name	FREEDOM DR
Stop Condition-Street 2	Signal
Street 2 Name	N/A
Stop Condition-Street 1	N/A

/Possible Solution		Field Measurements/Component Compliance							
Possible Solutions:		Compli	ance Description	Data	Compliance	Description	Data		
Remove & Replace Entire	Ramp.	N/A	Ramp Length (in)	72.0	<b>Yes</b> Ran	np Slope (%)	8.0		
	-	No	Ramp Width (in)	47.5	<b>Yes</b> Ran	np XSlope (%)	2.0		
		N/A	Flare Type LT	N/A	N/A Flar	e Type RT	N/A		
		N/A	Flare Slope LT (%)	N/A	N/A Flar	e Slope RT (%)	N/A		
		N/A	Flare Traversable LT?	N/A	N/A Flar	e Traversable RT?	N/A		
V .		N/A	Landing Length (in)	N/A	<b>N/A</b> DW	S Provided?	N/A		
Surveyor Notes:		N/A	Landing Width (in)	N/A	<b>N/A</b> DW	S Contrast?	N/A		
N/A		N/A	Landing Slope (%)	N/A	<b>N/A</b> DW	S Length (in)	N/A		
		N/A	Landing X Slope (%)	N/A	N/A DW	S Full Width?	N/A		
		N/A	Landing Curb? (Y/N)	N/A	<b>N/A</b> DW	S Offset (in)	N/A		
		N/A	Shared Landing?	N/A					
PROW/ADA:		N/A	Gutter Ponding?	N/A	<b>N/A</b> Gut	ter Slope (%)	N/A		
Not Found, R304.5.1		N/A	Gutter Lip Ht (in)	N/A	<b>N/A</b> Gut	ter X Slope (%)	N/A		
·		N/A	Painted X Walk1?	Yes	<b>N/A</b> Pair	nted X Walk2?	N/A		
			X Walk 1 Direction	To E	ΧW	alk 2 Direction	N/A		
		N/A	X Walk 1 Width (in)	114.0	N/A X W	alk 2 Width (in)	N/A		
			X Walk 1 Slope (%)	2.5	ΧW	/alk 2 Slope (%)	N/A		
			X Walk 1 X Slope (%)	2.5	ΧW	/alk 2 X Slope (%)	N/A		
		N/A	Ramp inside XWalk1?	Yes	<b>N/A</b> Rar	np inside XWalk2?	N/A		
			Road Slope (%)	N/A	N/A Cle	ar Space?	N/A		
			Road X Slope (%)	N/A	N/A Cle	ar Space to XWalk (in)	N/A		
		N/A	Any Obstructions?	N/A	N/A Sto	m Grate/Utility Hazard?	N/A		
Total Cost:	\$ 1850.00		Obstruction Type		Sto	m Grate/Utility Type			
				N/A			N/A		





