

# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

|                                                                                      |                     |                                                                                                   |                      |                                         |                       |                        |            |                          |      |
|--------------------------------------------------------------------------------------|---------------------|---------------------------------------------------------------------------------------------------|----------------------|-----------------------------------------|-----------------------|------------------------|------------|--------------------------|------|
| Intersection ID: 10037649                                                            |                     | Main Street: SEVENTY_SEVEN_CENTER_DR                                                              |                      | Cross Street: N/A                       |                       | Location: NW           |            |                          |      |
| ADA ID: FC6C597E63CA                                                                 |                     | Ramp Type: PerpDiag                                                                               |                      | Initial Pass/Fail: Pass                 |                       | Overall Compliance: No |            | Severity Score: 10       |      |
| Codes/Mitigation Info/Possible Solution                                              |                     |                                                                                                   |                      | Field Measurements/Component Compliance |                       |                        |            |                          |      |
|      |                     | Possible Solutions:                                                                               |                      | Compliance                              | Description           | Data                   | Compliance | Description              | Data |
|                                                                                      |                     | Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Remove & Replace Gutter. |                      | N/A                                     | Ramp Length (in)      | 47.0                   | Yes        | Ramp Slope (%)           | 5.4  |
|                                                                                      |                     |                                                                                                   |                      | Yes                                     | Ramp Width (in)       | 48.0                   | Yes        | Ramp XSlope (%)          | 0.8  |
|                                                                                      |                     |                                                                                                   |                      | N/A                                     | Flare Type LT         | Sloped                 | N/A        | Flare Type RT            | N/A  |
|                                                                                      |                     |                                                                                                   |                      | N/A                                     | Flare Slope LT (%)    | 2.4                    | Yes        | Flare Slope RT (%)       | 7.8  |
|                                                                                      |                     |                                                                                                   |                      | N/A                                     | Flare Traversable LT? | Yes                    | N/A        | Flare Traversable RT?    | Yes  |
|                                                                                      |                     | Surveyor Notes:<br><br>N/A                                                                        |                      | No                                      | Landing Length (in)   | N/A                    | Yes        | DWS Provided?            | Yes  |
|                                                                                      |                     |                                                                                                   |                      | No                                      | Landing Width (in)    | N/A                    | Yes        | DWS Contrast?            | Yes  |
|                                                                                      |                     |                                                                                                   |                      | No                                      | Landing Slope (%)     | N/A                    | Yes        | DWS Length (in)          | 24.0 |
|                                                                                      |                     |                                                                                                   |                      | No                                      | Landing X Slope (%)   | N/A                    | Yes        | DWS Full Width?          | Yes  |
| N/A                                                                                  | Landing Curb? (Y/N) |                                                                                                   |                      | No                                      | No                    | DWS Offset (in)        | 4.0        |                          |      |
| PROW/ADA:<br><br>Not Found, R304.2.1, R304.2.2-Perp, R304.3.2-Para, R304.5.3, R305.2 |                     | N/A                                                                                               | Shared Landing?      | N/A                                     |                       |                        |            |                          |      |
|                                                                                      |                     | Yes                                                                                               | Gutter Ponding?      | No                                      | Yes                   | Gutter Slope (%)       | 2.2        |                          |      |
|                                                                                      |                     | Yes                                                                                               | Gutter Lip Ht (in)   | 0.0                                     | No                    | Gutter X Slope (%)     | 2.4        |                          |      |
|                                                                                      |                     | N/A                                                                                               | Painted X Walk1?     | No                                      | N/A                   | Painted X Walk2?       | No         |                          |      |
|                                                                                      |                     |                                                                                                   | X Walk 1 Direction   | To S                                    |                       | X Walk 2 Direction     | To E       |                          |      |
|                                                                                      |                     | N/A                                                                                               | X Walk 1 Width (in)  | N/A                                     | N/A                   | X Walk 2 Width (in)    | N/A        |                          |      |
|                                                                                      |                     |                                                                                                   | X Walk 1 Slope (%)   | 4.9                                     |                       | X Walk 2 Slope (%)     | 2.6        |                          |      |
|                                                                                      |                     |                                                                                                   | X Walk 1 X Slope (%) | 1.7                                     |                       | X Walk 2 X Slope (%)   | 1.5        |                          |      |
|                                                                                      |                     | N/A                                                                                               | Ramp inside XWalk1?  | N/A                                     | N/A                   | Ramp inside XWalk2?    | N/A        |                          |      |
|                                                                                      |                     |                                                                                                   | Road Slope (%)       | 2.3                                     | N/A                   | Clear Space?           | Yes        |                          |      |
|                                                                                      | Road X Slope (%)    | 2.8                                                                                               | N/A                  | Clear Space to XWalk (in)               | N/A                   |                        |            |                          |      |
|                                                                                      | Any Obstructions?   | No                                                                                                | Yes                  | Storm Grate/Utility Hazard?             | No                    |                        |            |                          |      |
|                                                                                      | Obstruction Type    |                                                                                                   |                      | Storm Grate/Utility Type                |                       |                        |            |                          |      |
|                                                                                      |                     |                                                                                                   |                      |                                         |                       | N/A                    |            |                          | N/A  |
|                                                                                      |                     |                                                                                                   |                      |                                         |                       |                        | Yes        | Surface Condition? (G/P) | Good |
|                                                                                      |                     |                                                                                                   |                      | Total Cost: \$ 3950.00                  |                       |                        |            |                          |      |

