

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 5977	Main Street: HENBANE_CT			Street:	PIMPERNEL_RD	Location:	NW		
ADA ID: FC849C9AF285	Ramp Type: Perp			Pass/Fa	ail: Fail Overall (o Severity Score:	0		
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	HENDEANE OF	Possible Solutions:		Compliance Description Dat					Data
A Him-		Remove & Replace Entire Ram	n	N/A	Ramp Length (in)	48.0	Yes	Ramp Slope (%)	5.1
			γ.	Yes	Ramp Width (in)	73.0		Ramp XSlope (%)	0.9
				N/A	Flare Type LT	N/A		Flare Type RT	N/A
				N/A	Flare Slope LT (%)		N/A	Flare Slope RT (%)	N/A
S Mc				N/A	Flare Traversable LT?	N/A		Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A		DWS Provided?	N/A
		Surveyor Notes:		N/A	Landing Width (in)	N/A		DWS Contrast?	N/A
		N/A		N/A	Landing Slope (%)		N/A	DWS Length (in)	N/A
		1/2		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A		DWS Offset (in)	N/A
Arrent Contraction of the second of		1		N/A	Shared Landing?	N/A			
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		N/A		N/A	Gutter Lip Ht (in)	N/A		Gutter X Slope (%)	N/A
		N/A		N/A	Painted X Walk1?	No		Painted X Walk2?	N/A
Street 1 Name PIMPERNEL RD					X Walk 1 Direction	To SE		X Walk 2 Direction	N/A
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
					X Walk 1 Slope (%)	5.6		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	2.4		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?		N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
	1071				Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A		Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type	
		······ • ···· •				N/A			N/A



