cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 4727	Main Street: BRIGGS_DR				Cross Street: LOWEN_RD				Location:	
ADA ID: FCFE663F64E0		Ramp Type: PerpDiag			Initial Pass/Fail: Fail Overall Compliand			nce. N		
Codes/Mitigation Info/Possible Solution				Interal	Field Measurements/Component Compliance					
Possible Solutions:				Compliance Description Data Compliance Description Data						
				A <i>P</i> (1)			52.0	Yes		
		Remove & Replace Curb F Two New Directional Ram	-	with	N/A No	Ramp Length (in) Ramp Width (in)	52.0 36.0	No	Ramp Slope (%)	6.8 9.0
		Equivalent.			NO N/A	1 ()	36.0 N/A	NO N/A	Ramp XSlope (%)	9.0 N/A
						Flare Type LT			Flare Type RT	
					N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
		Surveyor Notes:			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A			N/A	Landing Slope (%)	N/A		DWS Length (in)	N/A
		a			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
A A A A A A A A A A A A A A A A A A A					N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
					N/A	Shared Landing?	N/A			
		PROW/ADA:			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		Not Found, R304.5.1, R30	4.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
and the second of the					N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
	Topol - A					X Walk 1 Direction	To NW		X Walk 2 Direction	To SW
					N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	LOWEN RD					X Walk 1 Slope (%)	1.1		X Walk 2 Slope (%)	10.1
Stop Condition-Street 2	None					X Walk 1 X Slope (%)	8.9		X Walk 2 X Slope (%)	3.4
Street 2 Name	BRIGGS DR				N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	StopSign					Road Slope (%)	9.8	N/A	Clear Space?	N/A
	. •					Road X Slope (%)	5.7	N/A	Clear Space to XWalk (in)	N/A
					N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost:	\$	3200.00		Obstruction Type			Storm Grate/Utility Type	
			•			51	N/A			N/A
								1		

s Surface Condition? (G/P)

Good

