

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 31337 Main Street: OLDBRIAR_LN Cross Street: RUSTIC_VIEW_CT Location: E

ADA ID: FD1BE8C6F5ED Ramp Type: BlendTrans2 Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 33.75

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name
RUSTIC VIEW CT
Stop Condition-Street 1
StopSign
Street 2 Name
N/A
Stop Condition-Street 2
N/A

Possible Solutions:

Remove & Replace Curb Ramp With
Two New Directional Ramps or
Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.5.1, R304.5.3

Total Cost: \$ 3200.00

Compliance Description Data Compliance Description Data Yes BlendTrans Slope (%) N/A Ramp Length (in) 96.0 3.6 No No Ramp Width (in) 45.0 BlendTrans XSlope (%) 9.3 N/A N/A Flare Type LT N/A Flare Type RT N/A N/A Flare Slope LT (%) N/A N/A Flare Slope RT (%) N/A N/A Flare Traversable LT? N/A N/A Flare Traversable RT? N/A N/A Landing Length (in) N/A N/A DWS Provided? N/A N/A Landing Width (in) N/A N/A **DWS Contrast?** N/A N/A N/A N/A Landing Slope (%) DWS Length (in) N/A N/A Landing X Slope (%) N/A N/A DWS Full Width? N/A N/A Landing Curb? (Y/N) N/A N/A DWS Offset (in) N/A N/A N/A Shared Landing? N/A **Gutter Ponding?** N/A N/A Gutter Slope (%) N/A N/A Gutter Lip Ht (in) N/A N/A Gutter X Slope (%) N/A N/A Painted X Walk1? No N/A Painted X Walk2? N/A X Walk 1 Direction To W X Walk 2 Direction N/A N/A X Walk 1 Width (in) X Walk 2 Width (in) N/A X Walk 1 Slope (%) 4.6 X Walk 2 Slope (%) N/A X Walk 1 X Slope (%) 3.0 X Walk 2 X Slope (%) N/A N/A N/A Ramp inside XWalk2? N/A Ramp inside XWalk1? N/A Road Slope (%) 3.0 Clear Space? N/A N/A Road X Slope (%) Clear Space to XWalk (in) N/A 4.6 N/A N/A N/A Any Obstructions? Storm Grate/Utility Hazard? N/A **Obstruction Type** Storm Grate/Utility Type N/A N/A

Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

12.8





