

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 31461 Main Street: SENEY\_DR Cross Street: SKIP\_STONE\_DR Location: S

ADA ID: FD1E747729E5 Ramp Type: PerpDiag Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 17.5

## **Codes/Mitigation Info/Possible Solution**

## Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 2
Street 2 Name
Stop Condition-Street 1

SKIP STONE DR StopSign SENEY DR None Possible Solutions:

Remove & Replace Curb Ramp With
Two New Directional Ramps or
Equivalent.

Surveyor Notes:
N/A

PROW/ADA:
Not Found, R304.5.1

Total Cost: \$ 3200.00

Compliance Description Data Compliance Description Data Yes Ramp Slope (%) N/A Ramp Length (in) 47.5 6.5 Yes Ramp XSlope (%) No Ramp Width (in) 35.0 0.4 N/A N/A Flare Type LT N/A Flare Type RT N/A N/A N/A N/A Flare Slope RT (%) N/A Flare Slope LT (%) N/A Flare Traversable LT? N/A N/A Flare Traversable RT? N/A N/A N/A N/A DWS Provided? N/A Landing Length (in) N/A Landing Width (in) N/A N/A **DWS Contrast?** N/A N/A N/A N/A Landing Slope (%) DWS Length (in) N/A N/A Landing X Slope (%) N/A N/A DWS Full Width? N/A N/A Landing Curb? (Y/N) N/A N/A DWS Offset (in) N/A N/A N/A Shared Landing? N/A **Gutter Ponding?** N/A N/A Gutter Slope (%) N/A N/A Gutter Lip Ht (in) N/A N/A Gutter X Slope (%) N/A N/A Painted X Walk1? No N/A Painted X Walk2? No X Walk 1 Direction To NE X Walk 2 Direction To NW N/A N/A X Walk 1 Width (in) X Walk 2 Width (in) N/A X Walk 1 Slope (%) 1.9 X Walk 2 Slope (%) 2.1 X Walk 1 X Slope (%) 1.8 X Walk 2 X Slope (%) 1.4 N/A N/A N/A Ramp inside XWalk2? N/A Ramp inside XWalk1? Road Slope (%) 0.5 N/A Clear Space? N/A N/A Road X Slope (%) Clear Space to XWalk (in) N/A 1.6

N/A

N/A

N/A

Yes

Storm Grate/Utility Hazard?

Storm Grate/Utility Type

Surface Condition? (G/P)

N/A

N/A

Good







N/A

Any Obstructions?

**Obstruction Type**