


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 12695	Main Street: S_CALDWELL_ST	Cross Street: E TRADE ST	Location: SW
ADA ID: FD3A0F31B62F	Ramp Type: Perp	Initial Pass/Fail: Fail	Overall Compliance: No
		Severity Score: 8.75	

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance		
	Possible Solutions:		Compliance	Description	Data
	Remove & Replace Entire Ramp.		Yes	Ramp Slope (%)	7.3
			No	Ramp Width (in)	1.4
			N/A	Flare Type LT	N/A
			N/A	Flare Slope LT (%)	N/A
			N/A	Flare Traversable LT?	N/A
			N/A	Landing Length (in)	N/A
			N/A	Landing Width (in)	N/A
			N/A	Landing Slope (%)	N/A
			N/A	Landing X Slope (%)	N/A
<p>Surveyor Notes:</p> <p>N/A</p> <p>PROW/ADA:</p> <p>R304.5.1</p>			N/A	Flare Type RT	N/A
			N/A	Flare Slope RT (%)	N/A
			N/A	Flare Traversable RT?	N/A
			N/A	DWS Provided?	N/A
			N/A	DWS Contrast?	N/A
			N/A	DWS Length (in)	N/A
			N/A	DWS Full Width?	N/A
			N/A	DWS Offset (in)	N/A
			N/A	Shared Landing?	N/A
			N/A	Gutter Ponding?	N/A
			N/A	Gutter Lip Ht (in)	N/A
			N/A	Painted X Walk1?	N/A
			Yes	X Walk 1 Direction	N/A
			To NW	X Walk 2 Direction	N/A
			N/A	X Walk 1 Width (in)	N/A
			112.0	X Walk 2 Width (in)	N/A
			2.5	X Walk 2 Slope (%)	N/A
			2.2	X Walk 2 X Slope (%)	N/A
			N/A	Ramp inside XWalk1?	N/A
			Yes	Ramp inside XWalk2?	N/A
			N/A	Road Slope (%)	N/A
			N/A	Clear Space?	N/A
			N/A	Clear Space to XWalk (in)	N/A
			N/A	Storm Grate/Utility Hazard?	N/A
			N/A	Storm Grate/Utility Type	N/A
			N/A		N/A
			N/A	Surface Condition? (G/P)	Good
Total Cost:		\$ 1850.00			

