

Access Compliance Report Public Rights-of-Way (Curb Ramps)



 Intersection ID: 21739
 Main Street:
 IMPERIAL_CT
 Cross Street:
 ENGLAND_ST
 Location:
 SW

 ADA ID: FD3D196A1EE5
 Ramp Type:
 PerpDiag
 Initial Pass/Fail:
 Pass
 Overall Compliance:
 No
 Severity Score:
 20.25

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 2
Street 2 Name
Stop Condition-Street 1

IMPERIAL CT StopSign ENGLAND ST None Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

R304.5.3, R304.2.1, R304.2.2-Perp, R304.3.2-Para, R305

Total Cost: \$ 3200.00

| Field Measurements/Component Compliance | | | | | |
|---|-----------------------|--------|------------------------|-----------------------------|-------|
| Compliance Description | | Data | Compliance Description | | Data |
| N/A | Ramp Length (in) | 94.0 | Yes | Ramp Slope (%) | 7.2 |
| Yes | Ramp Width (in) | 48.0 | No | Ramp XSlope (%) | 2.9 |
| N/A | Flare Type LT | Sloped | N/A | Flare Type RT | N/A |
| N/A | Flare Slope LT (%) | 8.3 | Yes | Flare Slope RT (%) | 3.1 |
| N/A | Flare Traversable LT? | Yes | N/A | Flare Traversable RT? | Yes |
| No | Landing Length (in) | N/A | No | DWS Provided? | No |
| No | Landing Width (in) | N/A | N/A | DWS Contrast? | No |
| No | Landing Slope (%) | N/A | N/A | DWS Length (in) | N/A |
| No | Landing X Slope (%) | N/A | N/A | DWS Full Width? | No |
| N/A | Landing Curb? (Y/N) | No | N/A | DWS Offset (in) | N/A |
| N/A | Shared Landing? | N/A | | | |
| Yes | Gutter Ponding? | No | Yes | Gutter Slope (%) | 3.6 |
| Yes | Gutter Lip Ht (in) | 0.0 | Yes | Gutter X Slope (%) | 0.1 |
| N/A | Painted X Walk1? | No | N/A | Painted X Walk2? | No |
| | X Walk 1 Direction | To SE | | X Walk 2 Direction | To NE |
| N/A | X Walk 1 Width (in) | N/A | N/A | X Walk 2 Width (in) | N/A |
| | X Walk 1 Slope (%) | 1.4 | | X Walk 2 Slope (%) | 4.0 |
| | X Walk 1 X Slope (%) | 2.4 | | X Walk 2 X Slope (%) | 0.2 |
| N/A | Ramp inside XWalk1? | N/A | N/A | Ramp inside XWalk2? | N/A |
| | Road Slope (%) | 0.1 | N/A | Clear Space? | Yes |
| | Road X Slope (%) | 4.0 | N/A | Clear Space to XWalk (in) | N/A |
| Yes | Any Obstructions? | No | Yes | Storm Grate/Utility Hazard? | No |
| | Obstruction Type | | | Storm Grate/Utility Type | |
| | | N/A | | | N/A |
| | | | Yes | Surface Condition? (G/P) | Good |
| | | | | | |





