

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 32120Main Street: ALLENWOOD_RDCross Street: DUNDALK_RDLocation: WADA ID: FD546927B33CRamp Type: PerpInitial Pass/Fail: FailOverall Compliance: NoSeverity Score: 8.75

Codes/Mitigation Info/Possible Solution

Total Cost:

Field Measurements/Component Compliance



Street 1 Name	ALLENWOOD RD
Stop Condition-Street 2	None
Street 2 Name	N/A
Stop Condition-Street 1	N/A

Possible Solutions:	Co
Remove & Replace Entire Ramp.	N/A
·	No
	N/A
	N/A
	N/A
	N/A
Surveyor Notes:	N/A
N/A	N/A
	N/A
	N/A
	N/A
PROW/ADA:	N/A
Not Found, R304.5.1	N/A
	N/A
	N/A
	N/A



1850.00

Comp	liance Description	Data	Comp	liance	Description	Data
N/A	Ramp Length (in)	48.0	Yes	Ramp	Slope (%)	6.1
No	Ramp Width (in)	42.0	Yes	Ramp	XSlope (%)	0.8
N/A	Flare Type LT	N/A	N/A	Flare T	N/A	
N/A	Flare Slope LT (%)	N/A	N/A	Flare S	N/A	
N/A	Flare Traversable LT?	N/A	N/A	Flare T	N/A	
N/A	Landing Length (in)	N/A	N/A	DWS F	N/A	
N/A	Landing Width (in)	N/A	N/A	DWS (Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)		N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS F	Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS (Offset (in)	N/A
N/A	Shared Landing?	N/A				
N/A	Gutter Ponding?	N/A	N/A	Gutter	Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter	X Slope (%)	N/A
N/A	Painted X Walk1?	No	N/A	Painte	d X Walk2?	N/A
	X Walk 1 Direction	To SE		X Walk	2 Direction	N/A
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk	2 Width (in)	N/A
	X Walk 1 Slope (%)	2.3		X Walk	2 Slope (%)	N/A
	X Walk 1 X Slope (%)	0.1		X Walk	2 X Slope (%)	N/A
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp	inside XWalk2?	N/A
	Road Slope (%)	1.5	N/A	Clear S	Space?	N/A
	Road X Slope (%)	2.3	N/A	Clear S	Space to XWalk (in)	N/A
N/A	Any Obstructions?	N/A	N/A	Storm	Grate/Utility Hazard?	N/A
	Obstruction Type			Storm	Grate/Utility Type	
		N/A				N/A
			Yes	Surfac	e Condition? (G/P)	Good