


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 3253	Main Street: SUTTONVIEW_DR	Cross Street: SHADOW_PINE_DR	Location: NE
ADA ID: FD559739C8A7	Ramp Type: Perp	Initial Pass/Fail: Pass	Overall Compliance: No
		Severity Score: 5.25	

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance		
	Possible Solutions:		Compliance	Description	Data
	Remove & Replace Entire Ramp.		Yes	Ramp Length (in)	48.5
			Yes	Ramp Width (in)	48.0
			N/A	Flare Type LT	Sloped
			N/A	Flare Slope LT (%)	3.7
			N/A	Flare Traversable LT?	Yes
			Yes	Landing Length (in)	48.0
			Yes	Landing Width (in)	48.0
			Yes	Landing Slope (%)	0.8
			No	Landing X Slope (%)	4.5
			N/A	Landing Curb? (Y/N)	No
			N/A	Shared Landing?	No
			Yes	Gutter Ponding?	No
			Yes	Gutter Lip Ht (in)	0.0
			N/A	Painted X Walk1?	No
				X Walk 1 Direction	To W
			N/A	X Walk 1 Width (in)	N/A
				X Walk 1 Slope (%)	5.7
				X Walk 1 X Slope (%)	4.0
			N/A	Ramp inside XWalk1?	N/A
<p>Surveyor Notes:</p> <p>N/A</p> <p>PROW/ADA:</p> <p>R304.5.3, R304.2.3</p>			N/A	Flare Type RT	N/A
			No	Flare Slope RT (%)	12.9
			N/A	Flare Traversable RT?	Yes
			Yes	DWS Provided?	Yes
			Yes	DWS Contrast?	Yes
			Yes	DWS Length (in)	25.5
			Yes	DWS Full Width?	Yes
			Yes	DWS Offset (in)	2.0
			Yes	Gutter Slope (%)	3.6
			Yes	Gutter X Slope (%)	3.9
			N/A	Painted X Walk2?	N/A
				X Walk 2 Direction	N/A
			N/A	X Walk 2 Width (in)	N/A
				X Walk 2 Slope (%)	N/A
				X Walk 2 X Slope (%)	N/A
			N/A	Ramp inside XWalk2?	N/A
			N/A	Clear Space?	Yes
			N/A	Clear Space to XWalk (in)	N/A
			Yes	Storm Grate/Utility Hazard?	No
<p>Total Cost:</p> <p>\$ 1850.00</p>				Storm Grate/Utility Type	
			N/A		N/A
			Yes	Surface Condition? (G/P)	Good

