


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 8599	Main Street: HATERAS_AV	Cross Street: IRMA_ST	Location: NE
ADA ID: FD63FB44CBAB	Ramp Type: Perp	Initial Pass/Fail: Fail	Overall Compliance: No
Severity Score: 21.25			
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance	

		Possible Solutions:		<table><thead><tr><th>Compliance</th><th>Description</th><th>Data</th></tr></thead><tbody><tr><td>N/A</td><td>Ramp Length (in)</td><td>72.0</td></tr><tr><td>No</td><td>Ramp Width (in)</td><td>47.5</td></tr><tr><td>N/A</td><td>Flare Type LT</td><td>N/A</td></tr><tr><td>N/A</td><td>Flare Slope LT (%)</td><td>N/A</td></tr><tr><td>N/A</td><td>Flare Traversable LT?</td><td>N/A</td></tr><tr><td>N/A</td><td>Landing Length (in)</td><td>N/A</td></tr><tr><td>N/A</td><td>Landing Width (in)</td><td>N/A</td></tr><tr><td>N/A</td><td>Landing Slope (%)</td><td>N/A</td></tr><tr><td>N/A</td><td>Landing X Slope (%)</td><td>N/A</td></tr><tr><td>N/A</td><td>Landing Curb? (Y/N)</td><td>N/A</td></tr><tr><td>N/A</td><td>Shared Landing?</td><td>N/A</td></tr><tr><td>N/A</td><td>Gutter Ponding?</td><td>N/A</td></tr><tr><td>N/A</td><td>Gutter Lip Ht (in)</td><td>N/A</td></tr><tr><td>N/A</td><td>Painted X Walk1?</td><td>No</td></tr><tr><td></td><td>X Walk 1 Direction</td><td>To W</td></tr><tr><td>N/A</td><td>X Walk 1 Width (in)</td><td>N/A</td></tr><tr><td></td><td>X Walk 1 Slope (%)</td><td>3.5</td></tr><tr><td></td><td>X Walk 1 X Slope (%)</td><td>2.7</td></tr><tr><td>N/A</td><td>Ramp inside XWalk1?</td><td>N/A</td></tr><tr><td></td><td>Road Slope (%)</td><td>N/A</td></tr><tr><td></td><td>Road X Slope (%)</td><td>N/A</td></tr><tr><td>N/A</td><td>Any Obstructions?</td><td>N/A</td></tr><tr><td></td><td>Obstruction Type</td><td></td></tr><tr><td></td><td></td><td>N/A</td></tr></tbody></table>			Compliance	Description	Data	N/A	Ramp Length (in)	72.0	No	Ramp Width (in)	47.5	N/A	Flare Type LT	N/A	N/A	Flare Slope LT (%)	N/A	N/A	Flare Traversable LT?	N/A	N/A	Landing Length (in)	N/A	N/A	Landing Width (in)	N/A	N/A	Landing Slope (%)	N/A	N/A	Landing X Slope (%)	N/A	N/A	Landing Curb? (Y/N)	N/A	N/A	Shared Landing?	N/A	N/A	Gutter Ponding?	N/A	N/A	Gutter Lip Ht (in)	N/A	N/A	Painted X Walk1?	No		X Walk 1 Direction	To W	N/A	X Walk 1 Width (in)	N/A		X Walk 1 Slope (%)	3.5		X Walk 1 X Slope (%)	2.7	N/A	Ramp inside XWalk1?	N/A		Road Slope (%)	N/A		Road X Slope (%)	N/A	N/A	Any Obstructions?	N/A		Obstruction Type				N/A
		Compliance	Description	Data																																																																													
N/A	Ramp Length (in)	72.0																																																																															
No	Ramp Width (in)	47.5																																																																															
N/A	Flare Type LT	N/A																																																																															
N/A	Flare Slope LT (%)	N/A																																																																															
N/A	Flare Traversable LT?	N/A																																																																															
N/A	Landing Length (in)	N/A																																																																															
N/A	Landing Width (in)	N/A																																																																															
N/A	Landing Slope (%)	N/A																																																																															
N/A	Landing X Slope (%)	N/A																																																																															
N/A	Landing Curb? (Y/N)	N/A																																																																															
N/A	Shared Landing?	N/A																																																																															
N/A	Gutter Ponding?	N/A																																																																															
N/A	Gutter Lip Ht (in)	N/A																																																																															
N/A	Painted X Walk1?	No																																																																															
	X Walk 1 Direction	To W																																																																															
N/A	X Walk 1 Width (in)	N/A																																																																															
	X Walk 1 Slope (%)	3.5																																																																															
	X Walk 1 X Slope (%)	2.7																																																																															
N/A	Ramp inside XWalk1?	N/A																																																																															
	Road Slope (%)	N/A																																																																															
	Road X Slope (%)	N/A																																																																															
N/A	Any Obstructions?	N/A																																																																															
	Obstruction Type																																																																																
		N/A																																																																															
<table><thead><tr><th>Compliance</th><th>Description</th><th>Data</th></tr></thead><tbody><tr><td>Yes</td><td>Ramp Slope (%)</td><td>7.0</td></tr><tr><td>No</td><td>Ramp XSlope (%)</td><td>6.1</td></tr><tr><td>N/A</td><td>Flare Type RT</td><td>N/A</td></tr><tr><td>N/A</td><td>Flare Slope RT (%)</td><td>N/A</td></tr><tr><td>N/A</td><td>Flare Traversable RT?</td><td>N/A</td></tr><tr><td>N/A</td><td>DWS Provided?</td><td>N/A</td></tr><tr><td>N/A</td><td>DWS Contrast?</td><td>N/A</td></tr><tr><td>N/A</td><td>DWS Length (in)</td><td>N/A</td></tr><tr><td>N/A</td><td>DWS Full Width?</td><td>N/A</td></tr><tr><td>N/A</td><td>DWS Offset (in)</td><td>N/A</td></tr><tr><td>N/A</td><td>Gutter Slope (%)</td><td>N/A</td></tr><tr><td>N/A</td><td>Gutter X Slope (%)</td><td>N/A</td></tr><tr><td>N/A</td><td>Painted X Walk2?</td><td>N/A</td></tr><tr><td></td><td>X Walk 2 Direction</td><td>N/A</td></tr><tr><td>N/A</td><td>X Walk 2 Width (in)</td><td>N/A</td></tr><tr><td></td><td>X Walk 2 Slope (%)</td><td>N/A</td></tr><tr><td></td><td>X Walk 2 X Slope (%)</td><td>N/A</td></tr><tr><td>N/A</td><td>Ramp inside XWalk2?</td><td>N/A</td></tr><tr><td>N/A</td><td>Clear Space?</td><td>N/A</td></tr><tr><td>N/A</td><td>Clear Space to XWalk (in)</td><td>N/A</td></tr><tr><td>N/A</td><td>Storm Grate/Utility Hazard?</td><td>N/A</td></tr><tr><td></td><td>Storm Grate/Utility Type</td><td></td></tr><tr><td>N/A</td><td></td><td>N/A</td></tr><tr><td>Yes</td><td>Surface Condition? (G/P)</td><td>Good</td></tr></tbody></table>			Compliance	Description	Data	Yes	Ramp Slope (%)	7.0	No	Ramp XSlope (%)	6.1	N/A	Flare Type RT	N/A	N/A	Flare Slope RT (%)	N/A	N/A	Flare Traversable RT?	N/A	N/A	DWS Provided?	N/A	N/A	DWS Contrast?	N/A	N/A	DWS Length (in)	N/A	N/A	DWS Full Width?	N/A	N/A	DWS Offset (in)	N/A	N/A	Gutter Slope (%)	N/A	N/A	Gutter X Slope (%)	N/A	N/A	Painted X Walk2?	N/A		X Walk 2 Direction	N/A	N/A	X Walk 2 Width (in)	N/A		X Walk 2 Slope (%)	N/A		X Walk 2 X Slope (%)	N/A	N/A	Ramp inside XWalk2?	N/A	N/A	Clear Space?	N/A	N/A	Clear Space to XWalk (in)	N/A	N/A	Storm Grate/Utility Hazard?	N/A		Storm Grate/Utility Type		N/A		N/A	Yes	Surface Condition? (G/P)	Good				
Compliance	Description	Data																																																																															
Yes	Ramp Slope (%)	7.0																																																																															
No	Ramp XSlope (%)	6.1																																																																															
N/A	Flare Type RT	N/A																																																																															
N/A	Flare Slope RT (%)	N/A																																																																															
N/A	Flare Traversable RT?	N/A																																																																															
N/A	DWS Provided?	N/A																																																																															
N/A	DWS Contrast?	N/A																																																																															
N/A	DWS Length (in)	N/A																																																																															
N/A	DWS Full Width?	N/A																																																																															
N/A	DWS Offset (in)	N/A																																																																															
N/A	Gutter Slope (%)	N/A																																																																															
N/A	Gutter X Slope (%)	N/A																																																																															
N/A	Painted X Walk2?	N/A																																																																															
	X Walk 2 Direction	N/A																																																																															
N/A	X Walk 2 Width (in)	N/A																																																																															
	X Walk 2 Slope (%)	N/A																																																																															
	X Walk 2 X Slope (%)	N/A																																																																															
N/A	Ramp inside XWalk2?	N/A																																																																															
N/A	Clear Space?	N/A																																																																															
N/A	Clear Space to XWalk (in)	N/A																																																																															
N/A	Storm Grate/Utility Hazard?	N/A																																																																															
	Storm Grate/Utility Type																																																																																
N/A		N/A																																																																															
Yes	Surface Condition? (G/P)	Good																																																																															
Street 1 Name		IRMA ST																																																																															
Stop Condition-Street 2		StopSign																																																																															
Street 2 Name		N/A																																																																															
Stop Condition-Street 1		N/A																																																																															
Total Cost:		\$		1850.00																																																																													

