

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 15127 Main Street: EXECUTIVE CR Cross Street: REGAL OAKS DR Location: NW ADA ID: FD6B55366229 Ramp Type: Perp Initial Pass/Fail: Fail **Overall Compliance: No Severity Score:** 10

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



EXECUTIVE CR Street 1 Name Stop Condition-Street 2 StopSign Street 2 Name N/A Stop Condition-Street 1 N/A Possible Solutions: Remove & Replace Entire Ramp. Surveyor Notes: N/A Not Found, R304.5.1, R304.5.3

PROW/ADA: Total Cost: 1850.00

Field Measurements/Component Compilance						
Compliance Description			Data	Compliance Description		Data
N	I/A	Ramp Length (in)	58.0	Yes	Ramp Slope (%)	6.2
N	lo	Ramp Width (in)	47.0	No	Ramp XSlope (%)	4.8
N	I/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
N	I/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
N	I/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
N	I/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
N	I/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
١	I/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
N	I/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
١	I/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
١	I/A	Shared Landing?	N/A			
١	I/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
N	I/A	Gutter Lip Ht (in)	0.5	N/A	Gutter X Slope (%)	N/A
١	I/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
		X Walk 1 Direction	To S		X Walk 2 Direction	N/A
N	I/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
		X Walk 1 Slope (%)	0.9		X Walk 2 Slope (%)	N/A
		X Walk 1 X Slope (%)	5.2		X Walk 2 X Slope (%)	N/A
N	I/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
		Road Slope (%)	N/A	N/A	Clear Space?	N/A
		Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
١	N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Obstruction Type			Storm Grate/Utility Type	
			N/A			N/A
				Yes	Surface Condition? (G/P)	Good
_	100000	No. of the second secon				





