

Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 12962		Main Street: CENTRAL_AV		Cross Street: OAKLAND_AV		Location: S									
ADA ID: FD8695B20A75		Ramp Type: Directional1		Initial Pass/Fail: Fail		Overall Compliance: No		Severity Score: 12.5							
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance											
<div></div> <div>Possible Solutions:</div> <div>Remove & Replace Entire Ramp.</div> <div>Surveyor Notes:</div> <div>N/A</div> <div>PROW/ADA:</div> <div>R304.2.2</div> <div>Street 1 Name</div> <div>CENTRAL AV</div> <div>Stop Condition-Street 1</div> <div>None</div> <div>Street 2 Name</div> <div>N/A</div> <div>Stop Condition-Street 2</div> <div>N/A</div> <div>Total Cost:</div> <div>\$</div> <div>1600.00</div>				Compliance		Description		Data		Compliance		Description		Data	
				N/A		Ramp Length (in)		102.0		N/A		Grade Break?		N/A	
				Yes		Ramp Width (in)		70.5		N/A		Grade Break Slope (%)		0.0	
				No		Ramp Slope (%)		8.6		N/A		Grade Break XSlope (%)		0.0	
				Yes		Ramp XSlope (%)		0.4							
				N/A		Flare Type LT		N/A		N/A		Flare Type RT		N/A	
				N/A		Flare Slope LT (%)		N/A		N/A		Flare Slope RT (%)		0.0	
				N/A		Flare Traversable LT?		N/A		N/A		Flare Traversable RT?		N/A	
				N/A		Landing Length (in)		0.0		N/A		DWS Provided?		N/A	
				N/A		Landing Width (in)		0.0		N/A		DWS Contrast?		N/A	
				N/A		Landing Slope (%)		0.0		N/A		DWS Length (in)		N/A	
				N/A		Landing X Slope (%)		0.0		N/A		DWS Full Width?		N/A	
				N/A		Landing Curb? (Y/N)		N/A		N/A		DWS Offset LT (in)		N/A	
				N/A		Shared Landing?		N/A		N/A		DWS Offset RT (in)		N/A	
				N/A		Gutter Ponding?		0.0		N/A		Gutter Slope (%)		N/A	
				N/A		Gutter Lip Ht (in)		0.0		N/A		Gutter X Slope (%)		N/A	
				N/A		Painted X Walk1?		No				Road Slope (%)		0.1	
						X Walk 1 Direction		To N				Road X Slope (%)		0.8	
						X Walk 1 Width (in)		N/A				Clear Space?		N/A	
						X Walk 1 Slope (%)		0.1		N/A		Clear Space to XWalk (in)		N/A	
		X Walk 1 X Slope (%)		0.8		N/A		Storm Grate/Utility Hazard?		N/A					
N/A		Ramp inside XWalk1?		N/A				Storm Grate/Utility Type							
N/A		Any Obstructions?		N/A						N/A					
		Obstruction Type				Yes		Surface Condition? (G/P)		Good					
						N/A		N/A		Curb Slope (%)		7.1			